

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21012571/UGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0007563\_01

**Claimant Vehicle No :** SKD4104G **Insured Vehicle No :** SMV4609Z

Date of Loss: 10/12/2021 Nature of Claim: TP Claim No: MPC2021D0005462

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD4104G**

Make & Model: VOLKSWAGEN PASSAT CC, 1.8 TSI (A) Engine No: CDA159950

Reg. Date: 13/12/2010 (Man. Year: 2010) Chassis No: WVVZZZ3CZBE727500

Colour: Black Odometer: 266627 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40Z R18 Rear Tyre Size: 235/40Z R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                             | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                             | 23,545.50         | 12,886.49         | 10,659.01         | 45.27         |
| Miscellaneous Items                               | 0.00              | 0.00              | 0.00              |               |
| Labour                                            | 5,440.00          | 3,740.00          | 1,700.00          | 31.25         |
| Paintwork Labour                                  | 0.00              | 0.00              | 0.00              |               |
| Towing                                            | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>               | <b>28,985.50</b>  | <b>16,626.49</b>  | <b>12,359.01</b>  | <b>42.64</b>  |
| <b>Approved Total (Overridden) (S\$)</b>          |                   | <b>13,300.00</b>  |                   |               |
| <b>Nett Amount (S\$)</b>                          | <b>28,985.50</b>  | <b>13,300.00</b>  | <b>15,685.50</b>  | <b>54.11</b>  |
| <b>+ Loss of Use (11.0 x S\$100.00/day) (S\$)</b> |                   | 1,100.00          |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                     |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                       |                   | <b>14,407.45</b>  |                   |               |
| <b>Global Sum Settlement (S\$)</b>                |                   | <b>14,400.00</b>  |                   |               |

INSPECTION

Date of Assignment: 13/12/2021

Date Inspected: 13/12/2021 Inspected At:

Polymath Garage Pte Ltd - Kaki Bukit (HQ)  
1 Kaki Bukit Avenue 6, #01-15  
Singapore 417883

Estimated Period of Repair: 9.0 days

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 15 Mar 2022)                      |
| <b>Parts:</b>        | 143                                                                                                                                                                          | VOLKSWAGEN PASSAT CC 1.8 TSI (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKD4104G)                                                                                                                                    |                                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

### Recommended Parts

| No. | Qty | Part No. Particulars          | Condition                      | Repairer's  | Amount       |
|-----|-----|-------------------------------|--------------------------------|-------------|--------------|
| 1   | 1   | *FRONT BUMPER                 | Deformed / Torn                | 1,352.00 FL | *1,352.00 FL |
| 2   | 2   | *FRONT BUMPER SIDE HOLDER     | Not Necessary                  | 130.00 FL   | *- FL        |
| 3   | 1   | *FRONT BUMPER REINFORCEMENT   | Repair                         | 798.00 FL   | *- FL        |
| 4   | 1   | *FRONT BUMPER SPONGE          | Torn                           | 176.00 FL   | *176.00 FL   |
| 5   | 1   | *FRONT BUMPER LOWER GRILLE    | Not Necessary                  | 240.00 FL   | *- FL        |
| 6   | 2   | *FRONT BUMPER FOG LAMP        | Not Necessary                  | 772.00 FL   | *- FL        |
| 7   | 2   | *FRONT BUMPER FOG LAMP COVER  | Not Necessary                  | 348.00 FL   | *- FL        |
| 8   | 2   | *FRONT BUMPER CHROME TRIM     | Distorted                      | 150.00 FL   | *150.00 FL   |
| 9   | 1   | *FRONT BUMPER AIR GUIDE (TOP) | Cracked                        | 88.00 FL    | *88.00 FL    |
| 10  | 1   | *FRONT GRILLE                 | Cracked                        | 824.00 FL   | *824.00 FL   |
| 11  | 1   | *FRONT GRILLE LOGO            | Cracked                        | 92.00 FL    | *92.00 FL    |
| 12  | 1   | *HEADLAMP                     | N/S Cracked/ O/S Not Necessary | 2,444.00 FL | *867.24 FL   |
| 13  | 1   | *FRONT SUPPORT PANEL          | Repair                         | 1,180.00 FL | *- FL        |
| 14  | 1   | *BONNET                       | Buckled                        | 2,171.00 FL | *1,598.25 FL |
| 15  | 1   | *BONNET LOCK                  | Serviceable                    | 98.00 FL    | *- FL        |
| 16  | 2   | *FRONT SEAT BELT (ASSY)       | Activated                      | 1,310.00 FL | *1,090.00 FL |
| 17  | 2   | *REAR NUMBER PLATE LAMP       | Not Necessary                  | 136.00 FL   | *- FL        |
| 18  | 1   | *REAR BUMPER                  | Distorted                      | 1,335.00 FL | *1,335.00 FL |
| 19  | 2   | *REAR BUMPER SIDE HOLDER      | Bent                           | 150.00 FL   | *150.00 FL   |
| 20  | 1   | *REAR BUMPER REINFORCEMENT    | Dented                         | 567.00 FL   | *567.00 FL   |
| 21  | 1   | *REAR BUMPER REFLECTOR        | N/S Broken / O/S Not Necessary | 136.00 FL   | *65.00 FL    |
| 22  | 1   | *REAR BUMPER CENTRE CHROME    | Cracked                        | 198.00 FL   | *198.00 FL   |
| 23  | 2   | *REAR BUMPER SIDE CHROME      | Cracked                        | 135.00 FL   | *135.00 FL   |
| 24  | 1   | *REAR BUMPER CENTRE GUIDE     | Distorted                      | 195.00 FL   | *195.00 FL   |
| 25  | 1   | *REAR BUMPER TOW COVER        | Missing                        | 45.00 FL    | *45.00 FL    |
| 26  | 1   | *SET REVERSE SENSOR           | Shorted                        | 1,008.00 FS | *250.00 FS   |
| 27  | 1   | *REAR END PANEL               | Badly Dented                   | 995.00 FL   | *995.00 FL   |
| 28  | 1   | *REAR END PANEL TOP GARNISH   | Distorted                      | 249.00 FL   | *249.00 FL   |
| 29  | 2   | *TAILLAMP                     | N/S Broken / O/S Cracked       | 1,240.00 FL | *634.50 FL   |
| 30  | 1   | *BOOTLID                      | Dented                         | 1,780.00 FL | *1,780.00 FL |
| 31  | 1   | *BOOTLID LOCK                 | Twisted                        | 362.00 FL   | *362.00 FL   |
| 32  | 1   | *BOOTLID WEATHERSTRIPE        | Twisted                        | 147.00 FL   | *147.00 FL   |
| 33  | 1   | *BOOTLID REFLECTOR            | N/S Scratched                  | 760.00 FL   | *305.00 FL   |
| 34  | 1   | *BOOTLID INNER TRIM           | Not Necessary                  | 228.00 FL   | *- FL        |
| 35  | 2   | *BOOTLID HINGE                | Serviceable                    | 382.00 FL   | *- FL        |
| 36  | 1   | *VOLKSWAGEN LOGO              | Not Necessary                  | 120.00 FL   | *- FL        |
| 37  | 1   | *CC EMBLEM                    | Serviceable                    | 75.00 FL    | *- FL        |
| 38  | 1   | *TSI EMBLEM                   | Serviceable                    | 80.00 FL    | *- FL        |
| 39  | 1   | *REAR FENDER INNER TRIM       | Serviceable                    | 1,060.00 FL | *- FL        |
| 40  | 1   | *SPARE TYRE PANEL TOP COVER   | Warped                         | 385.00 FL   | *385.00 FL   |
| 41  | 1   | *REAR EXHAUST PIPE            | Repair                         | 1,280.00 FL | *- FL        |
| 42  | 1   | *BOOTLID LOCK                 | Repeated                       | 362.00 FL   | *- FL        |
| 43  | 1   | *FRONT NUMBER PLATE }         | Broken                         | 30.00 FS    | *40.00 FS    |
| 44  | 1   | *FRONT NUMBER PLATE HOLDER }  | Broken                         | 30.00 FS    | *- FS        |
| 45  | 1   | *SET FRONT BUMPER CLIPS       | Necessary                      | 50.00 FS    | *50.00 FS    |
| 46  | 1   | *SET FRONT GRILLE CLIPS       | Not Necessary                  | 30.00 FS    | *- FS        |

Report was unsubmitted during this print-out.

4/18/22, 1:42 PM

Adjuster Report

| No.                                                | Qty | Part No. | Particulars                           | Condition     | Repairer's | Amount              |
|----------------------------------------------------|-----|----------|---------------------------------------|---------------|------------|---------------------|
| 47                                                 | 1   |          | *REAR NUMBER PLATE }                  | Broken        | 30.00 FS   | *40.00 FS           |
| 48                                                 | 1   |          | *REAR NUMBER PLATE HOLDER }           | Broken        | 30.00 FS   | *- FS               |
| 49                                                 | 1   |          | *SET REAR BUMPER CLIPS                | Necessary     | 50.00 FS   | *50.00 FS           |
| 50                                                 | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Not Necessary | 20.00 FS   | *- FS               |
| 51                                                 | 1   |          | *SET REAR END PANEL SEALANT           | Necessary     | 60.00 FS   | *50.00 FS           |
| 52                                                 | 1   |          | *SET BOOTLID INNER TRIM CLIPS         | Not Necessary | 30.00 FS   | *- FS               |
| 53                                                 | 2   |          | *SET REAR FENDER INNER TRIM CLIPS     | Not Necessary | 60.00 FS   | *- FS               |
| F=Franchise part. S=SpcNett. L=ListItemDisc.       |     |          |                                       |               |            |                     |
| Sub Total (S\$)                                    |     |          |                                       |               |            | 26,003.00 14,264.99 |
| - List Item Discount on L Items 10.00/10.00% (S\$) |     |          |                                       |               |            | 2,457.50 1,378.50   |
| Total Parts (S\$)                                  |     |          |                                       |               |            | 23,545.50 12,886.49 |
| Report was unsubmitted during this print-out.      |     |          |                                       |               |            |                     |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                              |          |                 |                 |
| 1                               | PANEL BEATING                | New      | 2,400.00        | 1,600.00        |
| 2                               | SPRAY PAINTING               | New      | 2,000.00        | 1,800.00        |
| 3                               | WIRING                       | New      | 100.00          | 30.00           |
| 4                               | TO REMOVE & REFIT CONDENSER  | New      | 120.00          | 0.00            |
| 5                               | TO REMOVE & REFIT RADIATOR   | New      | 120.00          | 0.00            |
| 6                               | TO REMOVE REVERSE SENSOR     | New      | 100.00          | 50.00           |
| 7                               | TO REMOVE UPHOLSTERY         | New      | 150.00          | 80.00           |
| 8                               | TO TRANSFER BOOTLID FITTINGS | New      | 150.00          | 80.00           |
| 9                               | TO SPRAY TUFF COAT           | New      | 150.00          | 100.00          |
| 10                              | TO RMEOVE EXHAUST PIPE       | New      | 150.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                              |          | <b>5,440.00</b> | <b>3,740.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >