



Not Authorized
Lala
Mawu
13/12/21
1/5 & 13,300
Telephoto at 11:00
9 days

REPAIR ESTIMATE

Car Plate: SKD4104G
Make & Model: Volkswagen Passat

Date:

13/12/2021

1/5 13,300

Qty	Parts	Amount (\$S)
1	Front Bumper <i>DD/Torn</i>	1,352.00 ✓
2	Front Bumper Side Holder <i>11</i>	130.00 X
1	Front Bumper Reinforcement <i>2</i>	798.00 X
1	Front Bumper Sponge <i>Torn</i>	176.00 ✓
1	Front Bumper Lower Grille <i>11</i>	240.00 X
2	Front Bumper Fog Lamp <i>11</i>	772.00 X
2	Front Bumper Fog Lamp Cover <i>11</i>	348.00 X
2	Front Bumper Chrome Trim <i>Des</i>	150.00 ✓
2	Front Bumper Air Guide <i>top one</i>	88.00 ✓
1	Front Grille <i>one</i>	824.00 ✓
1	Front Grille Logo <i>one</i>	92.00 ✓
2	Headlamp <i>n/s crs o/s n/a 867.24</i>	2,444.00 1pc
1	Front Support Panel <i>2</i>	1,180.00 X
1	Bonnet <i>one 1598.28</i>	2,171.00 ✓
1	Bonnet Lock <i>one</i>	98.00 X
2	Front Seat Belt <i>assy Activated 545x2=1090</i>	1,310.00 ✓
2	Rear Number Plate Lamp <i>11</i>	136.00 X
1	Rear Bumper <i>DIS</i>	1,335.00 ✓
2	Rear Bumper Side Holder <i>one</i>	150.00 ✓
1	Rear Bumper Reinforcement <i>DD</i>	567.00 ✓
2	Rear Bumper Reflector <i>n/s BRO o/s n/a 65</i>	136.00 1pc
1	Rear Bumper Centre Chrome <i>one</i>	198.00 ✓
2	Rear Bumper Side Chrome <i>one</i>	135.00 ✓
1	Rear Bumper Centre Guide <i>DIS</i>	195.00 ✓
1	Rear Bumper Tow Cover <i>ms</i>	45.00 ✓
1	Reverse Sensor <i>short 1804</i>	1,120.00 250 S/N
1	Rear End Panel <i>Body DD</i>	995.00 ✓
1	Rear End Panel Top Garnish <i>Des</i>	249.00 ✓
2	Taillamp <i>n/s BRO o/s crs 3x7.25x2=634.50</i>	1,240.00 ✓
1	Bootlid <i>DD</i>	1,780.00 ✓
1	Bootlid Lock <i>7m</i>	362.00 ✓
1	Bootlid Weatherstripe <i>7m</i>	147.00 ✓
2	Bootlid Reflector <i>n/s scs 305.00</i>	760.00 1pc
1	Bootlid Inner Trim <i>11</i>	228.00 X
2	Bootlid Hinge <i>one</i>	382.00 X
1	Volkswagen Logo <i>11</i>	120.00 X
1	CC Emblem <i>one</i>	75.00 X



1	TSI Emblem	SUC	80.00	X
2	Rear Fender Inner Trim	SUC	1,060.00	X
1	Spare Tyre Panel Top Cover	magued	385.00	X
1	Rear Exhaust Pipe	R	1,280.00	X
1	Bootlid Lock	Repeat	362.00	X
Sub-total			25,695.00	
Less 10%			(2,569.50)	
Total Parts			23,125.50	

Qty	Special Nett Items		Amount (\$S)	
1	Front Number Plate	BRO	\$ 30.00	X
1	Front Number Plate Holder		\$ 30.00	X
1 SET	Front Bumper Clips	neu	\$ 50.00	✓
1 SET	Front Grille Clips	11	\$ 30.00	X
1	Rear Number Plate		\$ 30.00	X
1	Rear Number Plate Holder	BRO	\$ 30.00	X
1 SET	Rear Bumper Clips	neu	\$ 50.00	✓
1 SET	Rear End Panel Top Garnish Clips	11	\$ 20.00	X
1 SET	Rear End Panel Sealant	neu	\$ 60.00	SW
1 SET	Bootlid Inner Trim Clips	11	\$ 30.00	X
2 SET	Rear Fender Inner Trim Clips	11	\$ 60.00	X
Total Parts			420.00	

Qty	Labour Charges		Amount (\$S)	
	Panel Beating		\$ 2,400.00	1600
	Spray Painting		\$ 2,000.00	1800
	Wiring		\$ 100.00	30
	To Remove & Refit Condenser		\$ 120.00	X
	To Remove & Refit Radiator		\$ 120.00	X
	To Remove Reverse Sensor		\$ 100.00	SW
	To Remove Upholstery		\$ 150.00	80
	To Transfer Bootlid Fittings		\$ 150.00	80
	To Spray Tuff Coat		\$ 150.00	100
	To Remove Exhaust Pipe		\$ 150.00	X
Total Labour			5,440.00	

REPAIR ESTIMATE TOTAL

28,985.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 1378.4.99
102
P- 12406.49
S-N- 480
L- 3740
- 16626.49
202
13301