

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

13 December 2021

QUOTATION FOR ACCIDENT REPAIR OF GBD7434R FIAT DOBLO

THIRD PARTY INSURER: AIG

<u>S/No.</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear tailgate LH	1	\$ 1525.30 <i>bt</i>
2.	Rear tailgate "90 Multijet" emblem LH	1	\$ 108.60 <i>bt</i>
3.	Rear tailgate mechanism lock LH	1	\$ 290.50 <i>X ny</i>
4.	Rear tailgate inner board LH	1	297.20 \$ 310.60 <i>bt</i>
5.	Rear tailgate RH	1	1420.40 \$ 1874.50 <i>bt</i>
6.	Rear tailgate upper mechanism lock RH	1	\$ 290.50 <i>X ny</i>
7.	Rear tailgate upper lock striker RH	1	\$ 65.00 <i>X ny</i>
8.	Rear tailgate lock striker (center) RH	1	\$ 65.00 <i>X ny</i>
9.	Rear tailgate lower mechanism lock RH	1	240.37 \$ 290.50 <i>bt</i>
10.	Rear tailgate lower lock striker RH	1	\$ 65.00 <i>X ny</i>
11.	Rear tailgate weather strip (centre) LH RH	1	\$ 148.50 <i>bt</i>
12.	Rear weather strip	1	\$ 410.60 <i>bt</i>
13.	Rear bumper	1	627 \$ 797.80 <i>de</i>
14.	Rear bumper side retainer L/R	2	68.90 \$ 137.80 <i>de</i>
15.	Rear bumper reflector lamp L/R	2	98.60 \$ 197.20 <i>bt</i>
16.	Rear bumper reinforcement beam	1	\$ 475.30 <i>bt</i>
17.	Rear bumper towing cover	1	\$ 67.00 <i>de</i>
18.	Rear bumper outer protector	1	\$ 310.80 <i>de</i>
19.	Rear end panel	1	332.94 \$ 430.80 <i>bt</i>
20.	Rear end panel top garnish	1	\$ 187.60 <i>de</i>
Subtotal before discount			\$ 8048.90
Discount 10%			\$ 804.89
Subtotal 1			\$ 7244.01

21. Rear Tailgate "DOBLO" Emblem RH *1 net*

\$124.80

6611.41

5950.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*knownedged by Repairer

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

13 December 2021

QUOTATION FOR ACCIDENT REPAIR OF GBD7434R FIAT DOBLO

THIRD PARTY INSURER: AIG

<u>S/No.</u>	<u>Parts S/Nett</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear tailgate windscreen sealant LH	1	\$ 80.00 <i>40 one</i>
2.	Rear tailgate "70km/h" sticker LH	1	\$ 20.00 <i>one</i>
3.	Rear tailgate inner board clip	1	\$ 30.00 <i>one 20</i>
4.	Rear tailgate windscreen sealant RH	1	\$ 80.00 <i>40 one</i>
5.	Rear tailgate "6Pax" sticker RH	1	\$ 20.00 <i>one</i>
6.	Rear tailgate inner board clip RH	1	\$ 30.00 <i>one 20</i>
7.	Rear reverse sensor	1	\$ 350.00 <i>200 one</i>
8.	Rear bumper clip	1	\$ 30.00 <i>one</i>
9.	Rear end panel garnish clip	1	\$ 20.00 <i>one</i>
10.	Rear end panel sealant	1	\$ 50.00 <i>x one</i>
Subtotal 2			<u>\$ 710.00</u> <i>400</i>

Labour

To check wiring	\$ 80.00 <i>30</i>
To transfer rear tailgate component parts to new rear tailgate LH	\$ 100.00 <i>60</i>
To transfer rear tailgate component parts to new rear tailgate RH	\$ 100.00 <i>60</i>
To remove and reinstall rear windscreen glass LH	\$ 120.00 <i>60</i>
To remove and reinstall rear windscreen glass RH	\$ 120.00 <i>60</i>
To remove, replace and reinstall rear reverse sensor	\$ 120.00 <i>30</i>
To remove and reinstall rear interior trims, garnish, seat, etc for necessary repairs	\$ 150.00 <i>60</i>
To straighten, repair, realign on rear affected area and replace damaged parts	\$ 1100.00 <i>700</i>
To spray painting on affected area	\$ 1100.00 <i>700</i>

Total Labour Cost \$ 2990.00 *800*
1840

Total Cost Of Repairs (Total cost of parts + Total labour cost) \$ 10944.01 *8190.30*

2/5 hrs only after repair
5 days
tanfmin@khantho.com

4/5 \$6550, 5 days
#