

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 29 Dec 2021

## **Preliminary Advice**

Insured : SKS3250U  
Vehicle No  
TP Vehicle : SMM7147S Accident Date : 08/12/2021  
No  
Make : TOYOTA VIOS Assignment Date : 13/12/2021  
Date of : 17/12/2021 Est. Duration of : 4  
Inspection Repair  
Inspection At : HOCK WAH MOTOR WORKSHOP PTE LTD (BEDOK)  
BLK 3011, BEDOK INDUSTRIAL PARK E., #01-  
2008/2010/2012  
SINGAPORE 489977

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,005.83
Revised Amount	:S\$	2,167.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,167.60

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.