

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ CT1 21012576/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM 171475
hockwch

at Workshop m/s

of

Insured:

SKS32804

Policy No.

Claims No.

SNM21D207146/CO2


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

70k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

938c

Vehicle: IN / OUT

Date:

Person Contacted:

L7A 38100

Veh No:

SM 171475

Yr Regn:

11/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Vios

c.c

1496

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

26 4/6

T/Radio:

Insured / Std / NI / NA

Eng/No:

MR2B23F3901181708

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

8/1/21

D.O.I.

17/1/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27 Dec

11/1/22 informed Anya P/P 82220.86

11/01/22 @ 2.30pm confirmed with Anya P/P 82220.85 (Red 3838.73, 63%)

Date/Time, File Pass to?

☐

Preli. Report

1) 11/01/22

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

2220.85)

TOTAL

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3939C
ARIES LING MIN LI
NO 1B TEO KIM ENG ROAD

SINGAPORE 416397
TEL : FAX :
PH : 82334796
ATTN :

ESTIMATE BILL

Number : EB00005829
Date : 10/12/2021
Case No : AD00012231
Vehicle No : SMM7147S
Chassis : MR2B23F3901181768
Year of Mfr : 2019
Policy No : MQ002956
Model : TOYOTA VIOS 1.5 E (AUTO)

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	793.20	25	594.90
2	BOOTLID HINGE RH	1.0	65.80	25	49.35
3	BOOTLID HINGE LH	1.0	65.80	25	49.35
4	BOOTLID EMBLEM	1.0	50.70	25	38.03
5	BOOTLID LOGO - VIOS	1.0	45.60	25	34.20
6	BOOTLID LOGO - E	1.0	35.50	25	26.63
7	END PANEL	1.0	742.70	25	557.03
8	REAR BUMPER	1.0	521.00	25	390.75
9	REAR BUMPER RETAINER RH	1.0	154.80	25	116.10
10	REAR BUMPER RETAINER LH	1.0	154.80	25	116.10
11	REAR BUMPER CLIP	4.0	5.50	25	16.50
12	REAR BUMPER REINFORCEMENT	1.0	332.70	25	249.53
13	REAR BUMPER REFLECTOR RH	1.0	907.50	25	680.63
14	REAR BUMPER REFLECTOR LH	1.0	907.50	25	680.63
15	REAR FENDER INNER SHIELD LH	1.0	34.80	25	26.10
List Price - Parts Sub Total					3,625.83
16	REAR FENDER RH - REPAIR	1.0			
17	REAR FENDER LH - REPAIR	1.0			
18	SPARE TYRE PANEL - REPAIR	1.0			
19	REVERSE SENSOR	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					3,905.83
20	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
21	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
22	ANTI-RUST COATING	1.0	150.00	0	150.00
23	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,100.00
SINGAPORE DOLLARS : SIX THOUSAND FOUR HUNDRED TWENTY-SIX AND CENTS TWENTY-FOUR ONLY			Less Excess		0.00
			SUBTOTAL		6,005.83
			GST 7.00%		420.41
			TOTAL		6,426.24

Date of accident : 08/12/2021 07:00 PM. Place : PIE (CHANGI) NEAR TOA PAYOH

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Acknowledged by Repairer

Issued by : Anysia

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3939C
ARIES LING MIN LI
NO 1B TEO KIM ENG ROAD

SINGAPORE 416397
TEL : FAX :
PH : 82334796
ATTN :

ESTIMATE BILL

Number : EB00005836
Date : 17/12/2021
Case No : AD00012231
Vehicle No : SMM7147S
Chassis: MR2B23F3901181768
Year of Mfr 2019
Policy No MQ002956
Model : TOYOTA VIOS 1.5 E
(AUTO)

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	BOOT ANTENNA SENSOR <i>CNE</i>	1.0	71.00	25	53.25
	List Price - Parts Sub Total				53.25
	Parts Total				53.25
SINGAPORE DOLLARS : FIFTY-SIX AND CENTS NINETY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		53.25
			GST 7.00%		3.73
			TOTAL		56.98

Date of accident : 08/12/2021 07:00 PM. Place : PIE (CHANGI) NEAR TOA PAYOH

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE