LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21011329/T1VF3E2-1

Date: 23/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle SLJ5038P Insured Vehicle No: SNB9492C

No:

Date of Loss: 02/11/2021 Nature of Claim: TP Claim No: MFL2021D0004813

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ5038P**

VOLVO S60, 1.5 T2 (A) Engine No: Make & Model: B4154T51809281 Reg. Date: 14/12/2016 (Man. Year: 2016) Chassis No: YV1FS28C0H2429258

Colour: Odometer: 61421 km Black

Engine Capacity: 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18 Front Left Side: Rear Left Side: Goodyear 6 mm Goodyear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,096.60	2,812.83	2,283.77	44.81
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,780.00	1,740.00	1,040.00	37.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,876.60	4,552.83	3,323.77	42.20
	Approved Total (Overridden) (S\$)		3,600.00		
	Nett Amount (S\$)	7,876.60	3,600.00	4,276.60	54.30

INSPECTION

Date of Assignment: 08/11/2021

Date Inspected: 08/11/2021 Inspected At:

No. 68 Kaki Bukit Avenue 6, #01-09 ARK

Elite Performance (kaki Bukit) (HQ)

Singapore 417896

Estimated Period of Repair: 5.0 days

MOHD TAUFIKH BIN HAMID Manager: **VERON CHEN** Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2021)

Parts: 143 VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ5038P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,376.60 F	*1,376.60 FL
2	1		*REAR BUMPER L/H SIDE RETAINER	Necessary	112.40 F	*112.40 FL
3	1		*L/H SIDE SKIRT	Deformed	769.70 F	*769.70 FL
4	1		*L/H REAR FENDER (NPA)	Repair	0.00 F	*- FL
5	1		*L/H REAR DOOR	Repair	1,251.20 F	*-FL
6	1		*L/H REAR DOOR INNER LOCK	Not Necessary	426.70 F	*- FL
7	1		*L/H REAR SPORT RIM	Cut	780.00 FS	*780.00 FS
8	1		*L/H REAR TYRE	Not Necessary	380.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,096.60	3,038.70
			- List Item Discount o	n L Items 0.00/10.00% (S\$)	0.00	225.87
				Total Parts (S\$)	5,096.60	2,812.83
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,200.00	700.00
2	TO CHECK WIRING AND REWIRE	New	60.00	30.00
3	TO REMOVE AND REINSTALL REAR DOOR COMPONENTS	New	80.00	0.00
4	TO REMOVE AND REINSTALL REAR UNDERCARRIAGE	New	240.00	100.00
5	TO PERFORM 4 WHEEL ALIGNMENT	New	120.00	80.00
6	TO APPLY ANTI-RUST	New	80.00	30.00
7	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,000.00	800.00
	Gross Labo	our Cost (S\$)	2,780.00	1,740.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >