

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2112-305 TG
DATE : 10-Dec-2021
POLICY NO. : P10532789R00
VEHICLE REG. NO. : SJP6441T
VEHICLE MAKE : MITSUBISHI LANCER 1.6 ATO Motor Claim Department
MINDEF / SINGAPORE ARMED FORCES

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 50.00	\$ 50.00
4	Rear Fender RH	1	\$ 700.00	\$ 700.00
5	Rear Fender Shield RH	1	\$ 82.00	\$ 82.00
6	Rear Fender Shield Clips	10	\$ 5.00	\$ 50.00
7	Rear Door LH	1	\$ 580.00	\$ 580.00
8	Rear Door Handle Assy RH	1	\$ 95.00	\$ 95.00
9	Tail Lamp RH	1	\$ 490.00	\$ 490.00
Total Spare Parts				\$ 2,777.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
10	Spray Paint (Rear Bumper, Rear Fender RH & Rear Door RH)	1	\$ 700.00	\$ 700.00
11	Remove and Refit Accident Affected Area	1	\$ 800.00	\$ 800.00
12	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 150.00	\$ 150.00
13	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
14	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 1,800.00
Amount Before Excess				\$ 4,577.00
Add GST @ 7%				320.39
Total Amount Payable				\$ 4,897.39

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.