

Not Authorized  
L1 Reg &  
Penalty After Point  
4-5 days

Date: 13/12/2021  
Vehicle No: SLH417Y  
Model: TOYOTA PRIUS HYBRID 1.8CVT  
Chassis: JTDKB3FU103537280-2016  
Reg.Year: 2016

Third Party Insurer: INDIA  
Third Party Veh No: SL52512J  
Date of Accident: 12/12/2021  
Estimator: TING AN  
Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		RM \$929.00
2	REAR TAILGATE OUTER GARNISH COVER	1		CM \$891.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		RM \$75.00
4	REAR TAILGATE "PRIUS" EMBLEM	1		RM \$75.00
5	REAR TAILGATE "TOYOTA" EMBLEM	1		RM \$65.00
6	REAR TAILGATE INNER TRIM BOARD	1		RM \$251.00
7	REAR TAILGATE INNER LOCK	1		RM \$452.00
8	REAR TAILGATE WEATHERSTRIPE	1		RM \$360.00
9	REAR WINDSCREEN MOULDING	1		RM \$75.00
10	REAR BUMPER	1		RM \$448.00
11	REAR BUMPER SIDE BRACKET LH	1		RM \$112.00
12	REAR BUMPER SIDE BRACKET RH	1		RM \$112.00
13	REAR BUMPER LOWER GARNISH COVER	1		RM \$486.00
14	REAR BUMPER TOWING COVER	1		RM \$25.00
15	REAR BUMPER ANTENNA SENSOR	1		\$75.00
16	REAR BUMPER REINFORCEMENT	1		\$337.00
17	REAR UPPER TAIL LAMP LH	1		RM \$433.00
18	REAR LOWER TAIL LAMP LH	1		RM \$486.00
19	REAR UPPER TAIL LAMP RH	1		RM \$433.00
20	REAR LOWER TAIL LAMP RH	1		RM \$486.00
23	REAR END PANEL	1		\$629.00
24	REAR END PANEL UPPER COVERING	1		\$145.00
25	REAR FLOOR PANEL TOOLBOX TRAY	1		\$144.00
26	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1		RM \$504.00
SUB TOTAL				\$8,028.00
LESS 25%				-\$2,007.00
PARTS TOTAL				\$6,021.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1		RM \$50.00
2	REAR WINDSCREEN SEALANT	1		RM \$80.00
3	REAR BUMPER REVERSE SENSOR	1		RM \$300.00
4	REAR BUMPER CLIPS	1		RM \$60.00
5	REAR END PANEL JOINT SEALANT	1		\$60.00
6	REAR END PANEL UPPER COVERING CLIPS	1		RM \$40.00
S/N TOTAL				\$590.00

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

8A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 13/12/2021  
Vehicle No: SLH417Y  
Model: TOYOTA PRIUS HYBRID 1.8CVT  
Chassis: JTDKB3FU103537280-2016  
Reg.Year: 2016

Third Party Insurer: INDIA  
Third Party Veh No: SLS2512J  
Date of Accident: 12/12/2021  
Estimator: TING AN  
Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.	\$1,000.00	?
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR TAILGATE OUTER GARNISH COVER, REAR BUMPER, REAR END PANEL & ETC.	\$1,000.00	800
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.	nn \$150.00	X
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	nn \$120.00	X
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	500
TO TUFF KOTE & UNDERSEAL MATERIALS & ETC.	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	200
LABOUR TOTAL		\$2,600.00

TING AN

TOTAL

\$9,211.00

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

