

Snu 7490H 2015 May.
Mercedes Benz C180 1595cc

TPAXA
Cecilis.

WDD2050402R054704.

Rear Bumper	Deland	1449. ✓
Rear Bumper Clips.	144	50(SW) ✓
Rear Bumper Side Holder x 02	144	75 x 2 = 150 x
Rear Bumper lower Garnish.	144	365 ✓
Rear Bumper Tow Cover	Deland	55 ✓
Rear Bumper Reinforcement.	Dented	735 ✓
Rear Bumper Centre Guide	144	215 x
Reverse Sensor x 02	1 piece	275 x 2 = 550. 275
Tail lamp RH.	could	775 585.

3464

3017-60

SN: 50

SMU 7490H.

Panel Beating.

Spray Painting 580

Wiring.

To remove reverse sensor

~~400~~ 250

~~400~~ 250

~~50~~ 30

~~100~~ 50

total: 3747.60

H/s: 3K.
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3,000
2 days