

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : JINDU JAMES

BLK 3 FERNVALE CLOSE #07-06
S 797486

Estimate No: EST1507611

Date: 06 Dec 2021

Policy No: MT/00749178

Veh Reg No: SJZ2189X

Make/Model: HONDA STREAM 1.8X A

Chassis No: RN63000410

Engine No: R18A2000465

Reg. Date: 11/01/2010

ATTN: AXA INSURANCE

Your Ref No: TP 1221-6583

Claim Type: Third Party

Accident Date: 04/12/2021

TP Veh Reg No: SJC 143 L

Estimate Repair Cost to Vehicle No :SJZ2189X

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	704.9000	1 PC	704.90	
2 REAR BUMPER SIDE HOLDER	25.7000	2 PCS	51.40	
3 REAR BRAKE CLIPS	3.8000	10 PC	38.00	
4 REAR BUMPER TOW COVER	17.3000	1 PC	17.30	
5 REAR BOOT	991.1000	1 PC	991.10	
6 REAR BOOT STREAM WORDING	39.2000	1 PCS	39.20	
7 REAR BOOT HONDA EMBLEM	34.2000	1 PCS	34.20	
8 REAR BOOT RUBBER (ROUND)	138.2000	1 PC	138.20	
9 REAR FOAM	0.0000	1 PCS	0.0000	
10 REAR REINFORCEMENT	0.0000	1 PCS	0.0000	
11 REAR END PANEL	364.2000	1 PC	364.20	
12 REAR END PANEL TOP GARNISH	145.3000	1 PCS	145.30	
			2,523.80	
		Less 20%	504.76	2,019.04
Special Net				
13 REAR BUMPER SENSOR	220.0000	1 SET	220.00	
14 REAR NUMBER PLATE WITH CASING	35.0000	1 PC	35.00	
15 SEALANT	20.0000	2 PC	40.00	
16 SPONGE TAPE	20.0000	1 PCS	20.00	
			315.00	315.00
Labour				
17 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	
18 TO RESPRAY PAINT ON ACCIDENT PORTIONS	950.0000	1 JOB	950.00	
19 TO CHECK WIRING	30.0000	1 JOB	30.00	
20 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	
21 TO TUFF-KOTE	60.0000	1 JOB	60.00	
22 TO REMOVE, REFIX REAR GLASS	150.0000	1 JOB	150.00	
			2,070.00	2,070.00

