


ASS. REC. BY: Tang JH REF: CS/CT121012588/T. 43

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 452K
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS 4893H Yr Regn: 2015, April
Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mitsubishi Outlander 2.4 2360
Colour: Maroon A/C: Insured / Std / NI / NA
Sp. Reading: 125880 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JMYX1GF SWFZ001986
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235/55R18
R: 235/55R18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (P) / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 14/12/21 @ 142m
Survey held at N-51
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COR Is \$9300, 7days

red: 8142.44;46%

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format :

Lump Sum / L&A (?)

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ANG KIM HENG
 BLK 216 MARSILING LANE #07-818
 SINGAPORE 730216

Contact : 96234926

TAX INVOICE

Repair Code : CLM17026

Date in : 11/12/2021

Vehicle Num. : SKS4893H

Model : MITSUBISHI OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R

Chassis/Eng# : JMYXTGF3WFZ001986/4B12PL5271

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR BUMPER	1	985.60 <i>de</i>	985.60
REAR BUMPER BRACKET L/R	2	71.00 <i>de</i>	142.00
REAR BUMPER LOWER LID	1	631.00 <i>de</i>	631.00
REAR BUMPER LOWER LID CLIPS	12	3.00 <i>ne</i>	36.00
REAR BUMPER REFLECTOR L/R	2	90.00 <i>cu</i>	180.00
REAR BUMPER SIDE GARNISH L/R	2	128.00 <i>de</i>	256.00
REAR BUMPER SIDE RETAINER L/R	2	25.00 <i>de</i>	50.00
REAR END PANEL	1	650.00 <i>bt</i>	650.00
REAR END PANEL ANTENNA SENSOR	1	187.00 <i>cu</i>	187.00
REAR END PANEL INNER TOP GARNISH	1	158.00 <i>de</i>	158.00
REAR END PANEL KEYLESS SENSOR	1	98.00 <i>cu</i>	98.00
REAR FENDER INNER TRIM GARNISH L/R	2	<i>MX</i> 927.00 <i>RHole</i>	1,854.00
REAR FLOOR PANEL	1	714.00 <i>Rx</i>	714.00
REAR FLOOR PANEL CARGO TRAY BOX	1	285.00 <i>de</i>	285.00
REAR FLOOR PANEL TOP BOARD COVER	1	366.00 <i>de</i>	366.00
REAR SPARE TYRE CARRIAGE	1	425.00 <i>Rx</i>	425.00
REAR SPARE TYRE CARRIAGE BRACKET	1	198.00 <i>Rx</i>	198.00
REAR TAILGATE	1	1154.00 <i>bt</i>	1,154.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANG KIM HENG
BLK 216 MARSILING LANE #07-818
SINGAPORE 730216

Contact : 96234926

TAX INVOICE

Repair Code : CLM17026

Date in : 11/12/2021

Vehicle Num. : SKS4893H

Model : MITSUBISHI OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R

Chassis/Eng# : JMYXTGF3WFZ001986/4B12PL5271

REAR TAILGATE 'LOGO' EMBLEM	1	42.00	ne ✓	42.00
REAR TAILGATE 'MIVEC' EMBLEM	1	50.00	ne ✓	50.00
REAR TAILGATE 'OUTLANDER' EMBLEM	1	86.00	ne ✓	86.00
REAR TAILGATE BUTTON SENSOR SWITCH	1	78.00	X	78.00
REAR TAILGATE DAMPER L/R	2	182.00	X	364.00
REAR TAILGATE INNER PULL HANDLE	1	42.00	X	42.00
REAR TAILGATE INNER RUBBER SIDE STOPPER L/R	2	18.00	X	36.00
REAR TAILGATE INNER TRIM BOARD	1	260.00	an ✓	260.00
REAR TAILGATE LOCK STRIKER	1	28.00	X	28.00
REAR TAILGATE MECHANISM LOCK	1	428.00	bt ✓	428.00
REAR TAILGATE OUTER GARNISH	1	566.00	an ✓	566.00
REAR TAILGATE SIDE SENSOR L/R	2	484.00	dis ✓	968.00
REAR TAILGATE WEATHER STRIP	1	192.00	an ✓	192.00
REAR TAILGATE WINDSCREEN LOWER MOULDING	1	62.00	ne ✓	62.00
REAR TAILGATE WINDSCREEN MOULDING L/R	2	55.00	qpc ✓	110.00
REAR TAILLAMP L/R	2	680.00	an ✓	1,360.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANG KIM HENG
BLK 216 MARSILING LANE #07-818
SINGAPORE 730216

Contact : 96234926

TAX INVOICE

Repair Code : CLM17026

Date in : 11/12/2021

Vehicle Num. : SKS4893H

Model : MITSUBISHI OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R

Chassis/Eng# : JMYXTGF3WFZ001986/4B12PL5271

Subtotal before discount 13,041.60

Percentage discount 10% 1,304.16

Sub-total 1 11,737.44

REAR BUMPER CLIPS - SET	1	80.00	80.00
REAR BUMPER REVERSE SENSOR - SET	1	250.00	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	50.00	50.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	100.00
REAR FLOOR PANEL INSULATOR MAT	1	250.00	250.00
REAR TAILGATE 'C&C' EMBLEM	1	70.00	70.00
REAR TAILGATE CAMERA	1	700.00	700.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	60.00	60.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00
REAR TAILLAMP CLIPS L/R - SET	2	25.00	50.00

Subtotal before discount 1,815.00

Percentage discount 0% 0.00

Sub-total 2 1,815.00

Parts-total 13,552.44

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANG KIM HENG
BLK 216 MARSILING LANE #07-818
SINGAPORE 730216

Contact : 96234926

TAX INVOICE

Repair Code : CLM17026
Date in : 11/12/2021
Vehicle Num. : SKS4893H
Model : MITSUBISHI OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R
Chassis/Eng# : JMYXTGF3WFZ001986/4B12PL5271

LABOUR

To reset system after repair works	180.00	280.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30	60.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet (to FR)	60	140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1200	1,500.00
To remove and reinstall exhaust pipe.	X	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1000	1,500.00
To apply anti-rust chemical on repaired and replaced panel.	30	80.00
To remove, reinstall tailgate mechanism and check for function	60	80.00
Labour Total		3,890.00
Parts & Labour Total		17,442.44

*** This is a computer-generated document which requires no signature.***

page 4

Tanpik 97445745
WP 14/12/21
2/3 Resurvey after repair
- 7 days
Tanpik e 11/12/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: