

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

QUEK MENG CHER
57A EDGEDALE PLAINS #03-22
SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
Date in : 13/12/2021
Vehicle Num. : SLC7226L
Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
Chassis/Eng# : RC11108615/K24W1408758

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER	1	700.00	700.00
FRONT BUMPER FOGLAMP COVER L/R	2	46.10	92.20
FRONT BUMPER GRILLE	1	67.00	67.00
FRONT BUMPER LOWER COVER	1	147.10	147.10
FRONT BUMPER LOWER LID GARNISH L/R	2	94.40	188.80
FRONT BUMPER REINFORCEMENT	1	294.70	294.70
FRONT BUMPER SIDE RETAINER L/R	2	12.80	25.60
FRONT GRILLE	1	186.50	186.50
FRONT GRILLE 'LOGO' EMBLEM	1	23.40	23.40
FRONT GRILLE BASE	1	269.00	269.00
FRONT GRILLE BASE CLIPS	4	4.30	17.20
FRONT GRILLE LOWER MOULDING	1	147.50	147.50
FRONT GRILLE OUTER CHROME MOULDING	1	325.00	325.00
FRONT GRILLE SIDE MOULDING L/R	2	48.20	96.40
FRONT GRILLE UPPER MOULDING	1	153.20	153.20
FRONT HEADLAMP LOWER BRACKET L/R	2	34.90	69.80
FRONT HEADLAMP L/R	2	2281.90	4,563.80
REAR AIRCON COOLING UNIT ASSY	1	876.80	876.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

QUEK MENG CHER
 57A EDGEDALE PLAINS #03-22
 SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
 Date in : 13/12/2021
 Vehicle Num. : SLC7226L
 Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
 Chassis/Eng# : RC11108615/K24W1408758

REAR BUMPER	1	568.30	de	568.30
REAR BUMPER LOWER GARNISH L/R	2	112.00	ca	224.00
REAR BUMPER REFLECTOR L/R	2	45.90	ca	91.80
REAR BUMPER SIDE RETAINER L/R	2	19.10	de	38.20
REAR END PANEL	1	460.80	bt	460.80
REAR END PANEL ANTENNA SENSOR	1	59.30	ca	59.30
REAR END PANEL BUZZLE SENSOR	1	80.00	ca	80.00
REAR END PANEL INNER TOP GARNISH	1	103.60	de	103.60
REAR EXHAUST GASKET	1	32.00	ne	32.00
REAR EXHAUST RUBBER MOUNTING	2	35.00	de	70.00
REAR EXHAUST SILENCER BOX	1	877.20	bt	877.20
REAR FENDER AIR VENT L/R	2	27.70	RH x LH ca	55.40
REAR FENDER GLASS MOULDING L/R	2	55.00	RH x LH ne	110.00
REAR FENDER INNER TRIM GARNISH L/R	2	763.60	de	1,527.20
REAR FENDER INNER UPPER TRIM GARNISH L/R	2	57.60	RH x LH de	115.20
REAR FENDER L/R	2	1023.70	RH x LH bt	2,047.40
REAR FENDER OUTER CHROME MOULDING L/R	2	109.70	X	219.40
REAR FENDER OUTER PANEL L/R	2	164.50	RH x LH bt	329.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

QUEK MENG CHER
 57A EDGEDALE PLAINS #03-22
 SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
 Date in : 13/12/2021
 Vehicle Num. : SLC7226L
 Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
 Chassis/Eng# : RC11108615/K24W1408758

REAR FLOOR PANEL	1	1119.00	but	1,119.00
REAR FLOOR PANEL LH SIDE FRAME MEMBER	1	650.80	but	650.80
REAR FLOOR PANEL LOWER JACK BRACKET	1	198.00	bt	198.00
REAR FLOOR PANEL TRIM CARPET	1	394.00	fu	394.00
REAR FLOOR PANEL VERTICAL MEMBER	1	210.70	bt	210.70
REAR NUMBER PLATE LAMP L/R	2	31.80	X	63.60
REAR TAILGATE	1	1216.80	bt	1,216.80
REAR TAILGATE 'H' LOGO	1	26.30	ac	26.30
REAR TAILGATE CENTER REFLECTOR	1	280.40	ant	280.40
REAR TAILGATE DAMPER L/R	2	298.00	bt	596.00
REAR TAILGATE HINGES L/R	2	35.80	Rx	71.60
REAR TAILGATE INNER CENTER TRIM GARNISH	1	51.00	X	51.00
REAR TAILGATE INNER PULL GARNISH	1	28.70	dl	28.70
REAR TAILGATE INNER TRIM GARNISH	1	206.30	cue	206.30
REAR TAILGATE INNER UPPER TRIM GARNISH L/R	2	41.20	X	82.40
REAR TAILGATE LOCK	1	185.40	bt	185.40
REAR TAILGATE LOCK STRIKER	1	27.50	bb	27.50
REAR TAILGATE LOWER CHROME MOULDING	1	175.50	ant	175.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

QUEK MENG CHER
 57A EDGEDALE PLAINS #03-22
 SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
 Date in : 13/12/2021
 Vehicle Num. : SLC7226L
 Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
 Chassis/Eng# : RC11108615/K24W1408758

REAR TAILGATE OPENER SENSOR	1	105.30	<i>dis</i>	105.30
REAR TAILGATE REFLECTOR L/R	2	386.20	<i>cra</i>	772.40
REAR TAILGATE REVERSE CAMERA	1	1061.90	<i>cut</i>	1,061.90
REAR TAILGATE SPOILER	1	614.30	X	614.30
REAR TAILGATE SPOILER CLIPS	8	3.50	X	28.00
REAR TAILGATE WEATHER STRIP	1	117.40	<i>cut</i>	117.40
REAR TAILGATE WINDSCREEN GLASS	1	1031.30	<i>brw</i>	1,031.30
REAR TAILGATE WINDSCREEN GLASS MOULDING	1	195.00	<i>nc</i>	195.00
REAR TAILGATE WIPER ARM	1	42.60	X	42.60
REAR TAILGATE WIPER ARM COVER	1	9.50	X	9.50
REAR TAILGATE WIPER BLADE	1	41.30	X	41.30
REAR TAILGATE WIPER MOTOR	1	252.30	<i>bb</i>	252.30
REAR TAILGATE WIRE HARNESS	1	200.80	<i>cut</i>	200.80
REAR TAILLAMP INNER VERTICAL PANEL L/R	2	298.00	<i>RH Rp LH bb</i>	596.00
REAR TAILLAMP L/R	2	838.10	<i>cut</i>	1,676.20
REAR TAILLAMP LOWER GARNISH L/R	2	76.80	<i>dl</i>	153.60
REAR TAILLAMP PANEL L/R	2	131.70	<i>RH Rp LH bt</i>	263.40
REAR THIRD SAFETY BELT L/R	2	268.70	<i>RH X LH jm</i>	537.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

QUEK MENG CHER
 57A EDGEDALE PLAINS #03-22
 SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
 Date in : 13/12/2021
 Vehicle Num. : SLC7226L
 Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
 Chassis/Eng# : RC11108615/K24W1408758

Subtotal before discount 28,535.50

Percentage discount 20% 5,707.10

Sub-total 1 22,828.40

FRONT BUMPER CLIPS - SET	1	50.00	30 net	50.00
FRONT GRILLE CLIPS - SET	1	30.00	20 net	30.00
FRONT NUMBER PLATE	1	25.00	0 net	25.00
FRONT NUMBER PLATE HOLDER	1	50.00	45 net	50.00
REAR BUMPER CLIPS - SET	1	50.00	30 net	50.00
REAR BUMPER REVERSE SENSOR - SET	1	280.00	200 net	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	20 net	30.00
REAR FENDER GLASS SEALANT L/R	1 2	60.00	40 net	120.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	50.00	20 net	100.00
REAR FENDER INNER UPPER TRIM GARNISH CLIPS L/R - SET	2	30.00	net 30	60.00
REAR FENDER OUTER CHROME MOULDING CLIPS L/R - SET	2	30.00	net 30	60.00
REAR FLOOR PANEL INSULATOR MAT	1	280.00	120 net	280.00
REAR NUMBER PLATE	1	25.00	0 net	25.00
REAR NUMBER PLATE HOLDER	1	50.00	0 net	50.00
REAR TAILGATE INNER CENTER TRIM GARNISH CLIPS - SET	1	20.00	10 net	20.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

QUEK MENG CHER
 57A EDGEDALE PLAINS #03-22
 SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
 Date in : 13/12/2021
 Vehicle Num. : SLC7226L
 Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
 Chassis/Eng# : RC11108615/K24W1408758

REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	<i>200</i>	50.00
REAR TAILGATE INNER UPPER TRIM GARNISH CLIPS L/R - SET	2	20.00	<i>7 200</i>	40.00
REAR TAILGATE LOWER CHROME MOULDING CLIPS - SET	1	30.00	<i>1000</i>	30.00
REAR TAILGATE RECORDER CAMERA	1	800.00	<i>di 350</i>	800.00
REAR TAILGATE WINDSCREEN GLASS SEALANT	1	80.00	<i>600</i>	80.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	<i>200</i>	40.00
Subtotal before discount				2,270.00
Percentage discount 0%				0.00
Sub-total 2				2,270.00
Parts-total				25,098.40

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	<i>100</i>	120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	<i>30</i>	80.00
To reset system after repair works	<i>180</i>	400.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	<i>30</i>	80.00
To remove, reinstall tailgate windscreen	<i>120</i>	150.00
To remove, reinstall fender glass	<i>80</i>	300.00
To remove, reinstall petrol tank. (to FR)	<i>60</i>	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>60</i>	140.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

QUEK MENG CHER
 57A EDGEDALE PLAINS #03-22
 SINGAPORE 828682

Contact : 90887048

TAX INVOICE

Repair Code : CLM17028
 Date in : 13/12/2021
 Vehicle Num. : SLC7226L
 Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT
 Chassis/Eng# : RC11108615/K24W1408758

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1300	1,500.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	600.	900.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	60.	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2200	2,800.00
To apply anti-rust chemical on repaired and replaced panel.	100.	120.00
To remove n refix rear gate mechanism and check for function	60.	80.00
		6,850.00
		31,948.40

Labour Total 6,850.00
Parts & Labour Total 31,948.40

*** This is a computer-generated document which requires no signature.***

page 7

Tanjin 97495749
 'WP' 14/12/21
 L/S Resury after spr.
 15-16 days
 fangji @lhando.com
 Repair limit \$27k.
 MV - \$75K
 Rebate - 47813

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: