

# PAIR ESTIMATE\*

VEHICLE NO SHA9037K  
MAKE REG 14.11.2019  
MODEL IONIQ G2

10/12/21

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER TOW COVER		\$94.60
1	REAR BUMPER REFLECTOR RH		\$41.45
10	REAR BUMPER CLIPS		\$22.00
		\$2.20	
	<b>SUB TOTAL</b>		<b>\$1,519.30</b>
	<b>20.00%</b>		<b>\$303.86</b>
	<b>DISCOUNTED TOTAL</b>		<b>\$1,215.44</b>
1	REAR REVERSE SENSOR		\$180.00
1	REAR BUMPER NUMBER PLAT W/HOLDER		\$55.00
			<b>\$235.00</b>
	<b>Labour Charge</b>		
	Panel Beating		\$500.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Kote		\$60.00
	Remove/refix Reverse sensor		\$60.00
	<b>TOTAL LABOUR</b>		<b>\$980.00</b>
	<b>ESTIMATE TOTAL</b>		<b>\$2,430.44</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpiti 97445745  
WP 13/12/21 @ 340

02 days

PP Rising before part

Tanpiti @ Phantom

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: