CITYCAB PTE LID

REPAIR ESTIMATE*

VEHICLE NO

SHA9037K

MAKE

REG 14.11.2019

10/12/21

CHIANG/AIG

ODEL	IONIQ G2	¥				
Qty	Parts Description/ Lab	oour	Туре		Amount	,
	1 REAR BUMPER				\$459.40	y
	1 REAR BUMPER SIDE BRACKET R	H			\$55.80	
	1 REAR BUMPER REINFORCEMEN	†			\$394.80	
	1 REAR BUMPER CENTRE MOULD	ING			\$451.25	4
	1 REAR BUMPER TOW COVER				\$94.60	
	1 REAR BUMPER REFLECTOR RH				\$41.45	<
	10 REAR BUMPER CLIPS			\$2.20	\$22.00	a
		SUB TOTAL			\$1,519.30	
		20.00%			\$303.86	
	DISC	COUNTED TOTAL			\$1,215.44	
	1 REAR REVERSE SENSOR				\$180.00	m_
	1 REAR BUMPER NUMBER PLAT V	W/HOLDER			\$55.00	49-
					\$235.00	
	Labour Charge					
	Panel Beating				\$500.00	95
	Spray Painting Charge				\$300.00	25
	Check Lighting and Wiring				\$60.00	×
	Tuff Kote				\$60.00	
	Remove/refix Reverse sensor				\$60.00	30
		TOTAL LABOUR			\$980.00	
		ESTIMATE TOTAL			\$2,430.44	
	ESTIMATE TOTAL		-		32,430.44	
				iala. The final rancis	auantum will	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					
	be prepared after the vehicle is surve	yea by a motor Survey	or appointe	ed by the insurance (company.	
	I	Tanftri 97495745 -WP 13/12/21 0540				
			· W	D13/12/21	C 340	
			П	7 .		

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1/2 Mound before part faufillen e/khantour



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 57\$701 Mainline > 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701

Date/Time: 13.12.2021 09:00 Page : 1 JOB CARD Sales Order: Team: ARC Repair TP(CFSO)1 JC NO305497565 USTOMER REGN NO. SHA9037K MILEAGE CITYCAB PTE LTD MAKE HYUNDAI 1R/MS FUEL 7010070 USTOMER NO. 383 SIN MING DRIVE E.....1/2... 11.12.2021 11:20 Singapore SINGAPORE 575717 IONIQ(G3) 65551188 EL. (R) YR OF MANU. 14.11.2019 TARGET DATE (P) CHASSIS CODE KMHC851CVLU182699 COMPLETION DATE/TIME: ISCOUNT CARD NO. JOB DESCRIPTION Accident Date: 10.12.2021 NATURE: 3P 10.1.2021 FRONT S/NO LABOR CODE DESCRIPTION HECKED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE nowledgement Slip Exit Pass 16; 10.: Vehicle No.: SHA9037K LIMTS cle No.: SHA9037K ie of Service Advisor Signature/Date Name of Service Adviso Date e returned to Service Reception upon collection To be kept by Security Guard