



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

### ESTIMATE

Co Reg No : 1977014696

LKK Auto Consultants hence notify the Repairer of the following:

• To display damaged part(s) during repair

• No illegal modification(s) is allowed

• Supplementary item(s) must be approved and is subject to final inspection

MITSUBISHI MOTORS

GST Reg No : MR-8500111-X

| Invoice Name & Address  | Owner Name & Vehicle Info  |
|---|--|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 6419 1892 | Cust No/Name /Mr. PANG (PAN)<br>Reg No/Reg Date SMH357A / 09/01/201<br>Date In/Mileage / 0<br>Chassis No JMAXTGK1WJZ004786<br>Engine No 4B40GB9312<br>Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU<br>Colour/Trim W13 SILKY WHITE / BK BLACK |

| Account No  | Terms  | Date/Time Printed | CSE | Operator          | WIP No     |       |         |
|---|--------|-------------------|-----|-------------------|------------|-------|---------|
| KAX00008  | Credit | 13/12/2021/ 17:00 |     | 282 / Kevin Leong | 18661      |       |         |
| Description of Goods / Services   |        |                   |     | Qty               | Unit Price | Disc% | Amount  |
| E PNT88000<br>REPLACE FRONT BUMPER PANEL, FRT LH HEADLAMP PANEL & AFFECTED AREA |        |                   |     | 450               |            |       | 900.00  |
| E PNT98000<br>PAINT WORK ON FRT BUMPER PANEL                                    |        |                   |     | 350               |            |       | 350.00  |
| E PNT88000<br>REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR       |        |                   |     |                   |            |       | 120.00  |
| M SUNDRY<br>PERFORM RUST PREVENTION   |        |                   |     |                   |            |       | 40.00   |
| A 54900099<br>CHECK WIRING & CHASSIS ELECTRICAL SYSTEM                          |        |                   |     |                   |            |       | 30.00   |
| A 10028901<br>TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM        |        |                   |     |                   |            |       | 120.00  |
| M SUNDRY<br>TO SUPPLY FRONT NUMBER PLATE WITH FRAME                             |        |                   |     |                   |            |       | 50.00   |
| M SUNDRY<br>SUNDRIES  |        |                   |     |                   |            |       | 30.00   |
| M HEADLAMP ASSY, LH   |        |                   |     | 1.00              | 1986.00    | 23.00 | 1529.22 |
| M LAMP A, T/SIG & FOG, FR LH  |        |                   |     | 1.00              | 506.00     | 23.00 | 389.62  |
| M COVER, FR BUMPER  |        |                   |     | 1.00              | 382.00     | 23.00 | 294.14  |
| M FACE, FR BUMPER   |        |                   |     | 1.00              | 664.00     | 23.00 | 511.28  |
| M GARNISH, FR BUMPER SIDE   |        |                   |     | 1.00              | 73.00      | 23.00 | 56.21   |
| M GARNISH, FR BUMPER SIDE   |        |                   |     | 1.00              | 214.00     | 23.00 | 164.78  |
| M BRKT, F/BMPR T/SIG LAMP, LH   |        |                   |     | 1.00              | 17.00      | 23.00 | 13.09   |
| M BAR, FR BUMPER GUARD  |        |                   |     | 1.00              | 100.00     | 23.00 | 77.00   |
| M REINFORCEMENT, FR BUMPER  |        |                   |     | 1.00              | 555.00     | 23.00 | 427.35  |
| M REINFORCEMENT, FR BUMPER  |        |                   |     | 1.00              | 236.00     | 23.00 | 181.72  |
| M STAY, FR BUMPER   |        |                   |     | 1.00              | 9.00       | 23.00 | 6.93    |
| M REINF, FR BUMPER SIDE, LH   |        |                   |     | 1.00              | 35.00      | 23.00 | 26.95   |
| M BRACKET, FR BUMPER SIDE, LH   |        |                   |     | 1.00              | 18.00      | 23.00 | 13.86   |
| M EXTENSION, FR BUMPER  |        |                   |     | 1.00              | 318.00     | 23.00 | 244.86  |
| M GRILLE ASSY, RADIATOR   |        |                   |     | 1.00              | 486.00     | 23.00 | 374.22  |
| M COVER, FR BUMPER GRILLE   |        |                   |     | 1.00              | 302.00     | 23.00 | 232.54  |
| M PNL, HEADLAMP SUPT, UPR LH  |        |                   |     | 1.00              | 59.00      | 23.00 | 45.43   |

Estimate

BR  
X nn  
CUT (SILVER) (Dark)  
BR  
BR  
X nn  
X nn  
DD  
BT  
X nn  
CUT (SILVER)  
X nn  
X nn

Steve (LKK)  
14/12/21, 12:44  
OD- NA AL  
Excess - ?

Confirm &amp; accepted by

Supp  
Spray FRT LH Fender \$750

Stere (LKR)

14/12/21, 12-10-10

OD- M AL

Excell - ?

P/P

M Bt 5%

58 d/s

Nett

6229.20

7% GST on

Total Payable

6,229.20

436.04

6,665.24

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.