



AIG-OD CLAIM
SURVEY: 14/12/21
UKK-STEVE

VEHICLE NO : SMH 357 A

MODEL : MIT/ECLIPSE CROSS 1.5 TK

WIP : 18661

Material	: \$	<u>3,304.84</u>
Labour	: \$	<u>2,290.00</u>
Sub-Total	: \$	<u>5,594.84</u>
Less 2% Disc	: \$	<u>—</u>
Less Excess	: \$	<u>400.00</u>
Total	: \$	<u>5,194.84</u>
GST 7%	: \$	<u>363.64</u>
Grand Total	: \$	<u>5,558.48</u>
Finalise By/Date : <u>Umay on 28/12/21</u>		



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wkend)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 15/12/2021	Cust No/Name /Mr PANG (PAN) Reg No/Reg Date SMH357A / 09/01/2019 Date In/Mileage 14/12/2021/ 37668 Chassis/Package JMAXTGK1WJZ004786 /CS3P Engine No 4B40GB9312 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF Colour/Trim W13 SILKY WHITE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	28/12/2021/ 09:27	BLK	884 / Lauro Songcuan	18661		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							450.00
REPLACE FRONT BUMPER PANEL & AFFECTED AREAS							
E PNT98000							350.00
SPRAY PAINT ON FRONT BUMPER PANEL							
E PNT88000							80.00
REMOVE & INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR							
M SUNDRY							40.00
PERFORM RUST PREVENTION ON AFFECTED PORTIONS							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							20.00
SUNDRIES							
E PNT98000							350.00
SPRAY PAINT ON FRONT LH FENDER → Supp							
S SPECIALISTJOB							50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME							
E PNT88000							450.00
REPAIR FRONT SUPPORT PANEL → Supp,							
E PNT98000							350.00
SPRAY PAINT FRONT SUPPORT PANEL → Supp							
X EXC							-400.00
INSURANCE EXCESS							
X HEADLAMP ASSY,LH ✓					1.00	1986.00 23.00	1529.22
X COVER,FR BUMPER ✓					1.00	382.00 23.00	294.14
X FACE,FR BUMPER ✓					1.00	664.00 23.00	511.28
X GARNISH,FR BUMPER SIDE ?					1.00	73.00 23.00	56.21
X GARNISH,FR BUMPER SIDE ?					1.00	214.00 23.00	164.78
X REINFORCEMENT,FR BUMPER ?					1.00	236.00 23.00	181.72
X REINF,FR BUMPER SIDE,LH ?					1.00	35.00 23.00	26.95
X EXTENSION,FR BUMPER ✓					1.00	318.00 23.00	244.86
X FRONT BUMPER GARNISH → Supp,					1.00	384.00 23.00	295.68

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 15/12/2021	Cust No/Name	/Mr PANG (PAN)
	Reg No/Reg Date	SMH357A / 09/01/2019
	Date In/Mileage	14/12/2021/ 37668
	Chassis/Package	JMAXTGK1WJZ004786 /CS3P
	Engine No	4B40GB9312
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF
	Colour/Trim	W13 SILKY WHITE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 09:27	BLK	884 / Lauro Songcuan	18661

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT AIG - OD CLAIM DOA: 13/12/2021 SURVEY: STEVE (LKK) 14/12/2021 05 DAYS Pro Forma <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	3,304.84		Nett	5,194.84
Labour	2,180.00	7% GST on	5194.84	363.64
Standard Menu	0.00			
Specialist Job	50.00		Total Payable	5,558.48
Diagnostics Job	0.00			
Sundry/Others	-340.00			
Total(w/o GST)	5,194.84			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMH 357 A**

<u>Materials</u>		<u>Cost (\$)</u>
1	Front Bumper Garnish — CUT	384.00
	23% Discount	88.32
		<u>295.68</u>
<u>Labour</u>		
1	Spray Paint on Front LH Fender	350.00 ✓
2	Repair Front Support Panel	450.00 ✓
3	Spray Paint Front Support Panel	350.00 ✓
		<u>1,150.00</u>
	Labour & Materials	1,445.68
	7% GST	101.20
	Total	<u>1,546.88</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

CAR NO: SMH 357A

WIP: 18661

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Painting on fit LH fender	? / SUPP		Steve	14/12/21
2		? / SUPP			
3	REINFORCEMENT FR bumper	? / SUPP			
4	REINFORCEMENT FR bumper	? / SUPP			
5	GARNISH, FR bumper side upr LH	? / SUPP			
6	GARNISH, FR bumper side upr LH	? / SUPP			
7	Clip Bumper x 10	? / SUPP			
8		? / SUPP			
9	Repair FT support panel \$ 450	? / SUPP			
10	Painting FT support panel \$ 350	? / SUPP			
11	Repair working Day = 2 days	? / SUPP			
12		? / SUPP			
13	EXTENSION, FR bumper upr	? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Eclipse Cross 1.5

SURVEYOR: Steve - LKH



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Mr PANG (PAN)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMH357A / 09/01/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>JMAXTGK1WJZ004786</td></tr> <tr> <td>Engine No</td><td>4B40GB9312</td></tr> <tr> <td>Make/Model</td><td>MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU</td></tr> <tr> <td>Colour/Trim</td><td>W13 SILKY WHITE / BK BLACK</td></tr> </table>	Cust No/Name	/Mr PANG (PAN)	Reg No/Reg Date	SMH357A / 09/01/201	Date In/Mileage	/ 0	Chassis No	JMAXTGK1WJZ004786	Engine No	4B40GB9312	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU	Colour/Trim	W13 SILKY WHITE / BK BLACK
Cust No/Name	/Mr PANG (PAN)														
Reg No/Reg Date	SMH357A / 09/01/201														
Date In/Mileage	/ 0														
Chassis No	JMAXTGK1WJZ004786														
Engine No	4B40GB9312														
Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU														
Colour/Trim	W13 SILKY WHITE / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	13/12/2021/ 17:00		282 / Kevin Leong	18661		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	1	REPLACE FRONT BUMPER PANEL, FRT LH HEADLAMP PANEL & AFFECTED AREA	450				450 900.00
E PNT98000	1	PAINT WORK ON FRT BUMPER PANEL	350				350.00
E PNT88000		REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR					80 120.00
M SUNDRY		PERFORM RUST PREVENTION					40.00
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00
M SUNDRY		TO SUPPLY FRONT NUMBER PLATE WITH FRAME					50.00
M SUNDRY		SUNDRIES					70 30.00
M HEADLAMP ASSY, LH	BR		1.00	1986.00	23.00		1529.22
M LAMP A, T/SIG & FOG, FR LH			1.00	506.00	23.00		389.62
M COVER, FR BUMPER	BR CUT (Silver) (Black)		1.00	382.00	23.00		294.14
M FACE, FR BUMPER	BR		1.00	664.00	23.00		511.28
M GARNISH, FR BUMPER SIDE			1.00	73.00	23.00		56.21
M GARNISH, FR BUMPER SIDE			1.00	214.00	23.00		164.78
M BRKT, F/BMPR T/SIG LAMP, LH			1.00	17.00	23.00		13.09
M BAR, FR BUMPER GUARD			1.00	100.00	23.00		77.00
M REINFORCEMENT, FR BUMPER			1.00	555.00	23.00		427.35
M REINFORCEMENT, FR BUMPER			1.00	236.00	23.00		181.72
M STAY, FR BUMPER			1.00	9.00	23.00		6.93
M REINF, FR BUMPER SIDE, LH			1.00	35.00	23.00		26.95
M BRACKET, FR BUMPER SIDE, LH			1.00	18.00	23.00		13.86
M EXTENSION, FR BUMPER	CUT (Silver)		1.00	318.00	23.00		244.86
M GRILLE ASSY, RADIATOR			1.00	486.00	23.00		374.22
M COVER, FR BUMPER GRILLE			1.00	302.00	23.00		232.54
M PNL, HEADLAMP SUPT, UPR LH			1.00	59.00	23.00		45.43

Confirm & accepted by

Supp
 Spray FRT LH Fender \$350 ✓

P/P

My B/L 5%

3 dys

Nett

6229.20

6,229.20

Total Payable

6,665.24

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	GK1W XTHXR6 2018MY

Ref No. SP14 357A

Before to use MUT-3x not to check all
is BSA brand

2021.12.21

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
CORNER SENSOR/SONAR	SONAR_9D080000	C2230	FR corner sensor signal lost	Stored	
R		C2233	LH front sensor signal lost	Stored	
		C2231	FL corner sensor signal lost	Stored	
		C2232	RH front sensor signal lost	Stored	
ACC/FCM	ACCSCFCM_4B080004		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100	B2503	Nose view camera fault	Stored	
EPB	EPB_4C080000		No DTCS		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		No DTCS		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		
HUD	HUD_9E080000		No DTCS		

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW21091-00
V.C.I. Version		B179
Vehicle Information		GK1W 2018MY

For No. SMH357A

Off to use

MUT-3 not unit to Baa

2021.12.21

ball Baa Band

2500 Done by Zep A.C. Test done.
