

NINETEEN AUTOWERKS PTE LTD
436 TAMPINESS STREET 43 #07-97
SINGAPORE 520436
HP: 96741991(Vessie Foo)

Estimate for SBW9870E(Nissan Sylphy)

*FR BUMPER	\$577.10
*FR BUMPER RETAINER RH	\$32.60
*HEADLAMP RH	\$627.40
*FR FENDER RH	\$752.80
*FR FENDER LOWER BRACKET RH	\$32.70
*FR FENDER RETAINER RH	\$46.80
*FR FENDER SIGNAL LAMP RH	\$66.00
*FR FENDER SPLASH GUARD RH	\$158.00
*FR FENDER SPLASH GUARD CLIPS RH	\$61.00
*FR DOOR HINGE RH	\$64.00
*FR DOOR RH	\$1,105.65
*FR DOOR RH WEATHERSTRIP	\$110.20
*FR DOOR RH CHROME MOULDING	\$146.90
*FR DOOR RH GLASS REGULATOR	\$120.70
*FR DOOR RH GLASS MOTOR	\$693.30
*FR DOOR INNER TRIM BOARD RH	\$641.40
*FR DOOR INNER TRIM BOARD CLIPS RH	\$61.00
*FR DOOR SIDE VIEW MIRROR	\$419.20
*RR DOOR RH	\$915.65
*RR DOOR RH WEATHERSTRIP	\$110.20
*RR DOOR RH CHROME MOULDING	\$146.90
*FR ALLOY RIM RH	\$1,202.85
*FR TYRE RH	\$280.00
*FR RH SHOCK ABSORBER	\$428.60
*FR RH LOWER ARM	\$251.80
*FR RH WHEEL BEARING	\$407.70
*FR RH KNUCKLE ASSY	\$435.20
*FR RH DRIVE SHAFT	\$1,245.95
*FR RH AUTO ROLL BAR LINK	\$48.35
	<hr/>
	\$11,189.95
Less 10%	\$1,119.00
	<hr/>
	\$10,070.96

LABOR TO REMOVE AND REPLACE DAMAGED PARTS INCLUDING	1,100.00
REFITTING AND REPOSITIONING OF REPLACED PARTS	
SPRAY PAINTING MATERIALS AND RESPRAY OF REPLACED PARTS AND	1,200.00
AFFECTED PARTS NECESSARY FOR PAINT WORK	
TO CARRY OUT ANTI RUST TREATMENT	150
TO REMOVE AND REFIT TRIMS, UPHOLSTERY, GARNISH AND	250
NECESSARY PARTS FOR REPAIRS WORK	
REWIRING TO FACILITATE WORKS	80

UNDERCARRIAGE REPAIR WORKS INCLUDING REMOVING AND FIXING AXLE, ABSORBER, LOWER ARM, SPRING AND ALL OTHER AFFECTED	250
4 WHEEL ALIGNMENT	150
TRANSFER OF FRONT DOOR COMPARTMENTS AND COMPONENTS	120
	<u>\$3,300.00</u>
Total	\$13,370.96