



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21012614/Rqf3e2	
			Date: 28/02/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 1583M	Veh. Inspected	SLX 27E	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/12/21/5014	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	14/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520I	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WBAJR12010CD56047	Colour	WHITE	
Odometer	26738 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 R20	BRIDGESTONE	6 mm	
L/H Front Tyre	245/35 R20	BRIDGESTONE	6 mm	
R/H Rear Tyre	245/35 R20	BRIDGESTONE	6 mm	
L/H Rear Tyre	245/35 R20	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2021	Inspection Date	16/12/2021	
Survey held at	BIS AUTOMOBILES PTE LTD 30 TEBAN GARDENS CRESCENT, SINGAPORE 608927			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	