

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012615/T1TCN2**Date:** 28/12/2021REFERENCE

Insured/Claimant:	TAN SOON CHWEE	Policy No:	2070173124	
Date of Loss:	01/12/2021	Nature of Claim:	OD	Claim No: 2726428568SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX2084P		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM029387
Reg. Date:	30/12/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF44MA028635
Colour:	Blue	Odometer:	6890 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$176,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,486.00	2,342.00	3,144.00	57.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,652.00	1,602.00	4,050.00	71.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,138.00	3,944.00	7,194.00	64.59
+ GST 7.00/7.00% (S\$)	779.66	276.08	503.58	64.59
Nett Amount (S\$)	11,917.66	4,220.08	7,697.58	64.59

INSPECTION

Date of Assignment:	14/12/2021		
Date Inspected:	13/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$753.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,342.00 FS	*2,342.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP-UPPER	Not Necessary	112.00 FS	*- FS
4	1		*REAR BUMPER SECURING STRIP-LOWER	Not Necessary	223.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	249.00 FS	*- FS
6	1		*REAR BUMPER BRACKET-LH	*Check	204.00 FS	*- FS
7	1		*REAR LIGHT REFLECTOR OUTER-LH	*Check	43.00 FS	*- FS
8	1		*REAR LIGHT REFLECTOR INNER-LH (NPA)	Not Necessary	0.00 FS	*- FS
9	1		*LED TAIL LIGHT-LH	Not Necessary	1,019.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION-LH/RH	*Check	46.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP-LH/RH	*Check	166.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION UPPER-LH	*Check	44.00 FS	*- FS
13	1		*EXHAUST TRIM-LH	Not Necessary	354.00 FS	*- FS
14	1		*AERIAL RETAINER-LH	Not Necessary	26.00 FS	*- FS
15	1		*AERIAL TELEPHONE	Not Necessary	174.00 FS	*- FS
16	1		*REAR VENT TRIM	Not Necessary	68.00 FS	*- FS
17	1		*SUNDRIES	*Check	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	5,486.00 2,342.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR LHS REAR FENDER AND AND LHS TAILLAMP PANEL.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
3	TO RESPRAY REAR BUMPER,LHS REAR FENDER AND LHS TAILLAMP PANEL	New	3,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,652.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >