

(08/11/13) wef

ASS. REC. B#: Marcus

REF:

CS/AIG 21012616/49f3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour:

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

coe until 31-1-2023 sol 1yr.
note 84149

24/12/21 4/5 \$1600 confirmed w.h Alvin Cred \$3996.88, 71%)

Date/Time, File Pass to?

☐

Preli. Report

1) 24/12 trans

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

1600

)



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 15/12/2021 OUR REF: UAPL1502
REPAIR ESTIMATE TO THE VEHICLE HONDA CIVIC NO: SJC6485K

1 FRONT BONNET LOCK		\$ 214.60	X
1 L/H FRONT HEADLAMP ASSY (HID) UNIT	903.20	\$ 1,876.40	X
1 L/H FRONT HEADLAMP LOWER BRACKET		\$ 89.60	X
1 FRONT BUMPER FACE	692.40	\$ 883.60	X
1 FRONT BUMPER REINFORCEMENT		\$ 435.50	X
2 FRONT BUMPER SIDE RETAINER		\$ 117.60	X
1 FRONT RADIATOR GRILLE ASSY	224.60	\$ 378.80	X
		\$ 3,996.10	
		\$ 799.22	
		\$ 3,196.88	

LESS 20%.....

SPECIAL NETT:-

1 FRONT NUMBER PLATE ASSY	\$ 50.00	X
1 FRONT BUMPER LOWER SPOILER	\$ 450.00	X

LABOUR CHARGES:-

TO DISM/REWIRE DAMAGED PORTION	\$ 100.00	20
TO DISM/RENEW FRONT LOWER SPOILER	\$ 100.00	X
TO PANEL BEAT DAMAGED PORTION	\$ 800.00	250
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 800.00	300
TO SPRAY UNDERCOATING IN REPAIR	\$ 100.00	X
	\$ 5,596.88	

not allowed
LKK
14/12/21
L/S \$ 1600
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-1820.20
202
2-1456.16
L-570
2226.16
202
1620