

Our Job Ref No : 305497689
Date : 17/12/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Thevan
Vehicle Reg No. : SH 8715B CTPL

Fax :

11/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLQ2957U
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | \$3,167.44 |
| (b) Labour Charges | \$1,311.00 |
| Total for Part-By-Part Repair Cost | \$4,478.44 |
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature :
Name : Thevan.
Date : 17/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: Towing fee incurred

COMFORT DELGRO ENGINEERING

VEHICLE # SH 8715B
TOKIO MARINE
305497689

TYPE OF C: TP
 SURVEY B: LKK/THEVAN
 DATE : 07/12/21

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
HEADLAMP SUPPORT PANEL	1		\$949.30	Cut
		TOTAL	\$949.30	

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH8715B/13/12/2021 13:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER COVER	20.00	0.00	Cut / 430.90 FL
2	1		*FRT BUMPER CLIPS	20.00	0.00	nec / 22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	nec / 28.00 FL
4	1		*HEADLAMP LH	20.00	0.00	guy / 1,993.65 FL Cr
5	1		*DAY LIGHT LH	20.00	0.00	SVC X 642.50 FL
6	1		*FRT BUMPER SIDE MOULDING LH	20.00	0.00	SVC X 186.90 FL
7	1		*FRT FENDER LH	20.00	0.00	del / 588.80 FL DT
8	1		*EMBLEM - BLUE DRIVE RH	20.00	0.00	nec / 26.60 FL
9	1		*FRT WHEEL HUB CAP LH	20.00	0.00	scr / 346.40 FL
10	1		*FRT BUMPER MOULDING CENTRE UPPER	20.00	0.00	SVC / 368.50 FL
11	1		*FRT FENDER ADVERTISEMENT LOGO LH	x nn	0.00	0.00 nec / 100.00 F
Sub Total (\$)						4,734.25
- List Item Discount on L Items (\$)						926.85
Total Parts (\$)						3,807.40

ComfortDelGro Engineering Pte Ltd/SH8715B/13/12/2021 13:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700.00
2	SPRAY PAINTING CHARGE	New	500 600.00
3	TUFF KOTE	New	20 60.00
4	CHECK ALL LIGHTING	New	20 60.00
5	TOWING FEE	New	60.00
Gross Labour Cost (\$)			1,480.00

ComfortDelGro Engineering Pte Ltd/SH8715B/13/12/2021 13:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan@lkhauto.com

82235469

12/12/21 1600 bfr paint

P/P ~~45~~ after repair photo

3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: