

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012624/UTY3N2**Date:** 03/01/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00031592103
Claimant Vehicle No :	GBC1043E	Insured Vehicle No :	GBF8700E
Date of Loss:	11/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207219/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC1043E	Engine No:	ZD30277326K
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Chassis No:	JN1SC2F24Z0801827
Reg. Date:	06/04/2011 (Man. Year: 2011)	Odometer:	371931 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	165R13(D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,876.73	2,350.99	4,525.74	65.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,400.00	530.00	27.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,806.73	3,750.99	5,055.74	57.41
Approved Total (Overridden) (S\$)		3,000.00		

	(S\$)	8,806.73	3,000.00	5,806.73	65.94
	+ GST 7.00/7.00% (S\$)	616.47	210.00	406.47	65.94
	Nett Amount (S\$)	9,423.20	3,210.00	6,213.20	65.94

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 16/12/2021

Estimated Period of Repair: 4.0 days

Inspected At:

SME Motor Pte Ltd (Kaki Bukit)
 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jan 2022)	
Parts:	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC1043E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAIL BOARD	Dented/Bent	1,459.60 FN	*1,459.60 FN	
2	2		*REAR TAIL LAMP	Cracked	532.60 FN	*532.60 FN	
3	1		*REAR RH TAIL LAMP PANEL	Bent	70.00 FN	*70.00 FN	
4	1		*REAR FLOOR BOARD	Repair	4,819.40 FN	*- FN	
5	1		*REAR TAIL BOARD HINGE RH	Bent	288.90 FN	*288.90 FN	
6	1		*REAR TAIL BOARD LOCK RH	Serviceable	40.20 FN	*- FN	
7	1		*REAR RH CORNER RUBBER BUSH	Not Necessary	19.00 FN	*- FN	
8	1		*REAR TAIL BOARD 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS	
9	1		*REAR TAIL BOARD 12 PAX STICKER	Necessary	25.00 FS	*10.00 FS	
10	1		*REAR NUMBER PLATE	Bent	20.00 FS	*15.00 FS	
11	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS	
					Sub Total (\$\$)	7,599.70	2,586.10
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	722.97	235.11
					Total Parts (\$\$)	6,876.73	2,350.99

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	1,000.00	800.00
3	SPRAY PAINTING	New	900.00	580.00
			Gross Labour Cost (\$\$)	1,930.00
				1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >