



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr><td>Cust No/Name</td><td>/TAN ENG HONG</td></tr> <tr><td>Reg No/Reg Date</td><td>SMD6350A / 29/08/201</td></tr> <tr><td>Date In/Mileage</td><td>/ 52633</td></tr> <tr><td>Chassis No</td><td>KNAF3416MK5009840</td></tr> <tr><td>Engine No</td><td>G4FGJH702480</td></tr> <tr><td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr><td>Colour/Trim</td><td>4SS SILKY SILVER / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/TAN ENG HONG	Reg No/Reg Date	SMD6350A / 29/08/201	Date In/Mileage	/ 52633	Chassis No	KNAF3416MK5009840	Engine No	G4FGJH702480	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK
Cust No/Name	/TAN ENG HONG														
Reg No/Reg Date	SMD6350A / 29/08/201														
Date In/Mileage	/ 52633														
Chassis No	KNAF3416MK5009840														
Engine No	G4FGJH702480														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	13/12/2021/ 13:40	BLE	261 / Edwin Caina	43931			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000		2	1.5				2000.00	
RENEW FR BUMPER , FR SUPPORT & BONNET			4.5				1800	
REPAIR LHF FENDER & RHF FENDER							1400.00	
E PNT98000		1					100.00	
RESPRAY FR BUMPER , BONNET , LHF FENDER & RHF FENDER			4				80.00	
E PNT88000							30.00	
REMOVE & REFIT AC COND & RADIATOR							120.00	
M SUNDRY							50.00	
TOP UP AC GAS							120.00	
A 54900099							40	
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM							80.00	
A 10028901							20.00	
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								
SUPPLY FR NUMBER PLATE WITH CASING			BR					
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
SUPPLY BODY PNL SEALANT			MC					
M SUNDRY								
Sundries			REC					
M LAMP ASSY-HEAD,LH		1	x m		1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,RH		1	BR		1.00	1219.00	20.00	975.20
M COVER-FR BUMPER		1	BR		1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER		1	BR		1.00	262.00	20.00	209.60
M CAP-FRONT HOOK		1	MIS		1.00	9.00	20.00	7.20
M GRILLE ASSY-RADIATOR		1	BR		1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE		1	BR		1.00	38.00	20.00	30.40
M LAMP ASSY-FRONT FOG,LH		1	x m		1.00	303.00	20.00	242.40
M LAMP ASSY-FRONT FOG,RH		1	x m		1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER,LH		1	x m		1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,RH		1	CUT		1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,LH		1	x m		1.00	143.00	20.00	114.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN ENG HONG Reg No/Reg Date SMD6350A / 29/08/201 Date In/Mileage / 52633 Chassis No KNAF3416MK5009840 Engine No G4FGJH702480 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	13/12/2021/ 13:40	BLE	261 / Edwin Caina	43931
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE REPEATER,RH	?	1.00	143.00	20.00	114.40
M ABSORBER-FRONT BUMPER ENERGY	BR	1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR	?	1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60
M BEAM COMPLETE-FR BUMPER	DD	1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE	BR	1.00	675.00	20.00	540.00
M ORNAMENT-KIA NO.115	ACC	1.00	32.00	20.00	25.60
M PANEL ASSY-HOOD	DD	1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH	?	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH	?	1.00	43.00	20.00	34.40
M PAD-HOOD INSULATING	X	1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING PAD MTG	X	13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD	BT	1.00	103.00	20.00	82.40
M CONDENSER ASSY-COOLER	BT	1.00	687.00	20.00	549.60
M GUARD-AIR,LH	BR	1.00	28.00	20.00	22.40
M GUARD-AIR,RH	BR	1.00	28.00	20.00	22.40
M RADIATOR ASSY	BT	1.00	646.00	20.00	516.80
M BLOWER ASSY	?	1.00	656.00	20.00	524.80

SURVEYOR NAME: Steve (LKK)SURVEYOR SIGNATURE: 14/12/21, 11:00amDATE: DD-MMREMARKS: Excess - ?P/PMy Bel Sy8 days

Confirm & accepted by

• The customer must sign and stamp the estimate.
• The customer must sign and stamp the estimate.
• The customer must sign and stamp the estimate.
• The customer must sign and stamp the estimate.

Authorized signatory and company stamp

7% GST on **12018.40** **841.29**
Nett 12,018.40
Total Payable 12,859.69

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.