

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gabriel Wee

Date: 20 Dec 2021

Preliminary Advice

Vehicle No	: XE2706Z	Accident Date	: 05/12/2021
Make	: MAN TGS 18.320	Policy No.	: D19MFL0000768_02
Assignment Date	: 14/12/2021	Excess	: S\$0.00
Date of Inspection	: 16/12/2021	Est. Duration of Repair	: 2
Inspection At	: SIN SHENG AUTO WORKSHOP PTE LTD (HQ) 5 TUAS AVE 3 SINGAPORE 639405		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,676.95
Revised Amount	:S\$	4,021.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,021.95

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	26,033.00

Salvage Value	:S\$
Margin for Repair	:S\$ 53,967.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.