

SIN SHENG AUTO WORKSHOP PTE LTD

REGISTRATION NO.: 202019500G

NO. 5 TUAS AVE 3 SINGAPORE 639405

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

India International Insurance Pte Ltd

64 Cecil Street

#04/#05 IOB Building

Singapore 049 711

Attn: Motor Claims Department

Estimate No : ES2021/0042

Date : 14/12/2021

Vehicle No : XE2706Z

Make/Model : MAN / TGS 40.540

Date of Accident : 05/12/2021

Policy number : D19MFL0000768_02

S/N	Description	Qty	Unit Amount (S\$)	Amount (S\$)
<u>Parts</u>				
1	Front bumper towing covering <i>ca</i>	1	3,985.50	3,985.50
			Less 10%	(398.55)
			Part after disc	3,586.95 ✓

Nett

1	Front number plate with casing <i>bt</i>	1	40.00	40.00 <i>35</i>
			Parts total	3,626.95

Labour charges

To panel beating/repair front body }

To remove/replace above mentioned parts }

To spray painting on affected areas

Labour total 1,050.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
HP 90010068
2 days
P/P
EXCESS: TBA
REVERS

3586.95 TOTAL

435.00

4021.95

4,676.95

Rasy after repair