

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn191ngsautomotive@gmail.com
Reg No.: S3405718K

QUOTATION

No. : AQT-0053

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :
Our Ref. : AQT-0025/SJX2191
C. C. :
Date : 14/12/2021
Page : 1 of 2

Description

Qty

U/ Price
S\$

Amount
S\$

ACCIDENT ON 10/12/2021@16:30HRS INVOLVING SJU9636C & SLL6879L

ALONG STEVEN RD TWDS PIE

CLAIMS AGAINST SLL6879L (MSIG)

REPLACEMENT PART: KIA CERATO FORTE

FRT BUMPER	1	cm 653.90	653.90	L
FRT BUMPER RETAINER LH	1	34.50	34.50	L
HEADLAMP LH	1	866.70	866.70	X
HEADLAMP RETAINER LH	1	36.50	36.50	X
FRT FENDER LH	1	403.40	403.40	L
LINING, FRT FENDER LH	1	156.00	156.00	L
BONNET	1	1,091.70	1,091.70	A
FRT DOOR RH	1	1,017.00	1,017.00	L
REAR DOOR RH - REPAIR			0.00	

FRT FENDER RH - REPAIR

REAR FENDER RH - REPAIR

REAR BUMPER - REPAIR

SubTotal

LESS 10%

CLIPS, FRT BUMPER S.NETT

CLIPS, FENDER LINING S.NETT

TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY
COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER.

REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART.
REFIT INTO POSITION.

SPRAY PAINTING

CHECK WIRING & LIGHT FUNCTION

~~Pillar RH - Repair~~

~~Mirror RH~~

~~Coat RH / Handle RH~~

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10

20

-425.50

4.00

4.00

1,000.00

1,800.00

50.00

4,259.70

-425.50

40.00

80.00

1,000.00

1,800.00

50.00