

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn191ngsautomotive@gmail.com
Reg No.: S3405718K

QUOTATION

No. : AQT-0053

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :
Our Ref. : AQT-0025/SJX2191
C. C. :
Date : 14/12/2021
Page : 1 of 2

Description

Qty

U/ Price
S\$

Amount
S\$

ACCIDENT ON 10/12/2021@16:30HRS INVOLVING SJU9636C & SLL6879L

ALONG STEVEN RD TWDS PIE

CLAIMS AGAINST SLL6879L (MSIG)

REPLACEMENT PART: KIA CERATO FORTE

FRT BUMPER	1	cm	653.90	653.90	✓
FRT BUMPER RETAINER LH	1		34.50	34.50	✓
HEADLAMP LH	1		866.70	866.70	✓
HEADLAMP RETAINER LH	1		36.50	36.50	✓
FRT FENDER LH	1		403.40	403.40	✓
LINING, FRT FENDER LH	1		156.00	156.00	✓
BONNET	1		1,091.70	1,091.70	✓
FRT DOOR RH	1		1,017.00	1,017.00	✓
REAR DOOR RH - REPAIR				0.00	
FRT FENDER RH - REPAIR					
REAR FENDER RH - REPAIR					
REAR BUMPER - REPAIR					
SubTotal				4,259.70	
LESS 10%				-425.50	
CLIPS, FRT BUMPER	S.NETT			4.00	✓
CLIPS, FENDER LINING	S.NETT			80.00	✓
TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER.	1		1,000.00	1,000.00	✓
REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.					
SPRAY PAINTING	1		1,800.00	1,800.00	✓
CHECK WIRING & LIGHT FUNCTION	1		50.00	50.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10

20

Pillar RH - Repair
Mirror RH
Cover RH ✓

cm

Handle RH

pd