

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 13/12/21
 VEHICLE NO: PA9781A
 DRIVER: LU BIN
 ATTENTION TO:
 PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
 Q REF No: Q21/12/1239
 DEPARTMENT: WTS Bus Department
 ACCIDENT DATE: 13/12/21
 REF No: JW-1221-51

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER FIBRE	1	2060	2,060.00
2	REAR BUMPER STRUCTURE FRAME	1	1730	1,730.00
3	REAR ENGINE COVER	1	1850	1,850.00
4	REAR ENGINE COVER STRUCTURE FRAME	1	1800	1,800.00
5	REAR LHS TAIL LAMP	1	380	380.00
6	REAR LHS CORNER PANEL	1	850	850.00
7	GAS SPRING	2	45	90.00
8	60KM/H STICKER	1	5	5.00
9	REAR NUMBER PLATE	1	30	30.00
10	WOODLANDS TRANSPORT STICKER	1	180	180.00
Labour Costs				
1	TO DISMANTLE AND REMOVE ALL NECESSARY ATTACHMENT ITEMS AND DAMAGED ITEMS REPLACE AFFECTED PARTS. TO REPAIR AND KNOCK REAR PANEL	1	2300	2,300.00
2	CHECK WIRING SYSTEM AND REMOVE REAR LHS TAIL LAMP AND REPLACE NEW PARTS.	1	200	200.00
Spray Paint				
1	Spray Painting TO PUTTY AND SPRAY PAINTING REAR BUMPER, REAR WHOLE ENGINE COVER. REAR LHS CORNER PANEL AND REAR PANEL. TO PATCH REAR WTS STICKER.	1	2400	2,400.00
TOTAL:				13,875.00
Total Amount				SGD 13,875.00

Remarks:

 13/12/21
 Signature of Workshop Dpt

 13/12/21
 Signature of Department Head


 Signature of Claim Department