

SERVE YOU MOTOR PTE LTD

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

INS: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

COMPANY: BUS TECH PTE LTD

Registration no. PC 3036 Y TOYOTA / HIACE HIGH ROOF COMMUTER TURBO AUTO

Acc/date: 9/12/2021

Date: 14-Dec-21

Quotation No. : 9123036

S/N	Qty	Particulars	Amount
-----	-----	-------------	--------

LIST ITEMS

1	1	Front Bumper Assy	582.70 ✓
2	2	Front Bumper Retainer	104.00 ✓
3	1	Front Bumper Bracket	138.00 X
			824.70
			Less: 25%
			-206.18
			\$ 618.53

LABOUR & MISC CHARGES

1	To dismantle / renew / knock / straighten the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	300.00 150%
4	Supply spray paint material and necessary items to respray the affected area / panel.	nn 350.00 X
		\$ 650.00

Total Parts and Labour Cost of Repair**\$ 1,268.53**

NOT ASKED
Painting After Pain
1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: