

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 28 Jan 2022

Preliminary Advice

Insured : SMD8898Z
Vehicle No
TP Vehicle No : GBA1945M
Accident Date : 12/12/2021
Make : MERCEDES-BENZ VITO 111
Assignment Date : 14/12/2021
Date of Inspection : 17/12/2021
Est. Duration of Repair : 5
Inspection At : TRUST AUTOWORKS - ANG MO KIO (HQ)
BLK 5035, #01-345 ANG MO KIO INDUSTRIAL PK 2
SINGAPORE 569538

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,635.30
Revised Amount	:S\$	4,992.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,992.30

Lump Sum Repair	:S\$	3,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	4,000.00
COE / PARF Rebate	:S\$	2,400.00

Salvage Value	:S\$	
Margin for Repair	:S\$	1,600.00

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
-
- (X) The above survey was conducted on a 'without prejudice' basis.