

08/11/13) wef

A9S, REC: BY: *Marcus*

REF:

CC6/AIG 21012640/4953

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *GRK 2300P*at Workshop m/s *24*

of _____

Insured: *GRK 6123H*

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$72k*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *5* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: *21A 820499*Veh No: *GRK 2300P*Yr Regn: *26/12/20*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CU /*Make: *Toyota Hiace*c.c *2982*Colour: *white*

A/C: Insured / Std / NI / NA

Sp. Reading: *49406*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTFH 702P 300249954*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: *F: 195-115*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *14/1/24*D.O.I. *14/1/24*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear & Rear window shattered

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*3 I involved 20/8800 have G.A**23/1/24 4/5 & 8200 confirmed with AGen*

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

S + RS, \$ _____

☐

Interview (\$ _____)

Photos _____

☐

Tech. Invs (\$ _____)

Others _____

☐

Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

TOTAL

cecilie

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorised
nkle

14/1/21

5 days 4/5 @ 8200/
Alfred. Atkinson

VEHICLE No: GBK 2300P

1PC	REAR WINDSCREEN	shattered	1399.00	\$1,499.80 ✓
1PC	REAR WIPER ARM	n1		\$245.50 X
1PC	REAR WIPER ARM MOTOR	11		\$655.10 X
1PC	REAR WIPER BLADE	11		\$108.00 X
1PC	TAILGATE	Body		\$2,159.10 ✓
1PC	TAILGATE OUTER HANDLE	one	341.10	\$455.80 ✓
1PC	TAILGATE INNER LOCK	one	398.50	\$425.80 ✓
1PC	TAILGATE INNER LOCK ACTUATOR	Damage / one	366.50	\$455.20 ✓
1PC	TAILGATE LOCK STRIKER	11		\$45.00 ✓
1PC	TAILGATE WEATHERSTRIP	two	361.20	\$399.80 X
2PCS	TAILGATE DAMPERS @\$366.10	11		\$732.20 X
1PC	TAILGATE INNER TRIM BOARD	one / torn	421.10	\$455.10 ✓
1PC	TAILGATE REAR LOGO	one		\$85.00 ✓
1PC	TAILGATE 'TOYOTA' STICKER	one		\$60.00 ✓
1PC	TAILGATE 'HACE' STICKER	one		\$62.00 ✓
1PC	REAR BUMPER	one	651.20	\$681.10 ✓
1PC	REAR BUMPER STEP BRACKET	one		\$166.80 X
4PCS	REAR BUMPER LOWER BRACKETS @\$35.00	one		\$140.00 ✓
2PCS	REAR BUMPER SIDE RETAINERS @\$105.00	one		\$210.00 ✓
1PC	REAR END PANEL OUTER	Body	801.10	\$981.10 ✓
1PC	REAR END PANEL INNER	Body	645.20	\$988.50 ✓
1PC	REAR END PANEL TOP STEEL PLATE	one		\$366.80 X
2PCS	TAILLAMPS @\$455.10	one	399.10 x 2 = 798.20	\$910.20 ✓
2PCS	TAILLAMP LOWER GARNISHS @\$165.00	one / two		\$330.00 ✓
2PCS	TAILLAMP HOUSING PANELS @\$488.50	one / one	408 x 2 = 816	\$977.00 ✓
1PC	REAR SPARE TYRE BRACKET	one		\$455.10 X
1PC	REAR SPARE TYRE BRACKET HOLDER	one		\$165.30 X
1PC	REAR FENDER	one		\$1,971.10 X
			(257)	\$16,186.40

S.NETT

1PC	REAR WINDSCREEN SEALANT	one	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	one	\$50.00 40
1PC	REAR LICENCE PLATE	one	\$50.00 X
1SET	REAR TAILGATE CORPORATE STICKER	one	\$500.00 300
1SET	TAILGATE INNER TRIM BOARD CLIPS	one	\$50.00 ✓
1SET	REAR BUMPER CLIPS	one	\$50.00 ✓
1SET	REAR BUMPER REVERSE SENSOR	shock	\$280.00 200
1PC	REAR END PANEL SEALANT	one	\$50.00 ✓
1PC	REAR WOODEN PLY WOOD	one	\$850.00 X

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	40
TO DISMANTLE & REPLACED REAR WINDSCREEN	\$150.00	100
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO SPRAY RUST PROOFING	\$120.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	850
TO PUTTY & SPRAY PAINTING	\$1,500.00	900
TOTAL	\$22,016.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-10045-30
252
P-7533-97
S-N-730
L-2070
10333-97
252
P-67