

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012643/UTY3N2**Date:** 04/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00031202100

Claimant Vehicle No : SMH2133R **Insured Vehicle No :** GBL1028C

Date of Loss: 09/12/2021 Nature of Claim: TP Claim No: SNM21D207180/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH2133R**

Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: A25A0139509

Reg. Date: 16/01/2019 (Man. Year: 2018) Chassis No: AXVH701027144

Colour: Black Odometer: 39771 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,084.45	5,016.08	1,068.37	17.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,135.00	1,635.00	500.00	23.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,219.45	6,651.08	1,568.37	19.08
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	8,219.45	5,300.00	2,919.45	35.52
+ GST 7.00/7.00% (S\$)	575.36	371.00	204.36	35.52
Nett Amount (S\$)	8,794.81	5,671.00	3,123.81	35.52

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At: NPH Auto Service (HQ)
Blk 9005 Tampines Steet 93, #01-246/254
Singapore 528839

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2022)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2133R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented/Buckled	1,143.70 FL	*1,143.70 FL
2	2		*REAR BOOT HINGE L&R	Not Necessary	430.00 FL	*- FL
3	1		*REAR BOOT CENTRE LOGO	Necessary	47.90 FL	*47.90 FL
4	1		*REAR NUMBER PLATE LAMP GARNISH	Repair	255.00 FL	*- FL
5	1		*REAR HYBRID SYENEGY DRIVE EMBLEM	Necessary	95.00 FL	*95.00 FL
6	2		*REAR BOOT LAMP L&R	Scratched/Cracked	1,168.80 FL	*1,168.80 FL
7	2		*REAR LAMP L&R	Cracked	1,780.40 FL	*1,780.40 FL
8	1		*REAR BOOT LOCK TOP	Twisted	399.50 FL	*399.50 FL
9	1		*REAR BOOT LOCK LOWER CATCH	Not Necessary	23.50 FL	*- FL
10	13		*REAR BOOT CARPET CLIPS	Not Necessary	65.00 FL	*- FL
11	1		*REAR BOOT RUBBER	Twisted	194.70 FL	*194.70 FL
12	1		*REAR BUMPER	Dented	655.14 FL	*655.14 FL
13	1		*REAR BUMPER LOWER SPOILER	Grazed	393.00 FL	*393.00 FL
14	1		*REAR LAMP CENTRE PANEL	Repair	651.00 FL	*- FL
15	1		*REAR LAMP CENTRE PANEL INNER GARNISH	Scratched/Cracked	296.20 FL	*296.20 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	227.10 FL	*227.10 FL
17	4		*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
18	1		*SET REAR BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,045.94	6,621.44
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,961.49	1,605.36
Total Parts (\$\$)	6,084.45	5,016.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL R/BOOT,R/LAMP,R/BOOT LAMP,R/BUMPER,CUT OUT & RENEW R/LAMP CENTRE PANEL,KNOCK SPARE TYRE PANEL,R/FENDER AND RESTRAIGHTHEN BODY & CHASSIS	New	950.00	580.00
2	SPRAY PAINTING	New	1,000.00	900.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	RENEW PARKING SENSOR	New	80.00	50.00
5	REMOVE & INSTALL REAR BOOT FINICHER	New	80.00	80.00
Gross Labour Cost (\$)			2,135.00	1,635.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >