



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203853

INV Date 20/06/2022

Reference CC4/LPC21012656/Uga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 5954M
Insured Veh. YN 281K
Claim No. 21/21/21/VC00/025252
Policy No. Z/20/VC05/005170
Accident Date 13/12/2021
Inspection Date 14/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21012656/Uga3q2 Date: 20/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 281K	Veh. Inspected	GBJ 5954M	
Policy No.	Z/20/VC05/005170	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025252	Excess (\$)	0.00	
Assign From	ENG HUEY NI	Assign Date	14/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFAT35YX0K213366	Colour	SILVER	
Odometer	81702 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	FALKEN	6 mm	
L/H Front Tyre	195 R15	FALKEN	6 mm	
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/12/2021	Inspection Date	14/12/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 5954M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	TAILLAMPS @\$295.20	CRACKED	590.40	590.40
2	TAILLAMP HOUSING PANELS @\$105.00	TO REPAIR SEE LABOUR	210.00	-
1	REAR LICENCE PLATE BRACKET	BENT	245.10	245.10
	LESS 25% DISCOUNT		-261.38	-208.88
			784.12	626.62
<u>SPECIAL NETT ITEMS</u>				
1	REAR CARGO BOX BACK DOOR N/S (SN)	BADLY DENTED	1,900.00	1,400.00
1	REAR CARGO BOX BACK DOOR LOCK BAR N/S (SN)	BENT	620.00	400.00
1	REAR CARGO BOX BACK DOOR INNER WOODEN N/S (SN)	CRACKED	900.00	600.00
1	REAR CARGO BOX BACK DOOR O/S (SN)	BADLY DENTED	1,900.00	1,400.00
1	REAR CARGO BOX BACK DOOR LOCK BAR O/S (SN)	BENT	620.00	400.00
1	REAR CARGO BOX BACK DOOR INNER WOODEN O/S (SN)	CRACKED	900.00	600.00
1	SET REAR CARGO BOX BACK DOOR CORPORATE STICKER (SN)	NECESSARY	680.00	350.00
1	REAR 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	14.00
1	REAR END PANEL (SN)	BENT	650.00	600.00
			8,490.00	5,974.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR .		80.00	50.00
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	180.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS .		1,080.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,500.00	380.00
			2,990.00	1,050.00
GRAND TOTAL			12,264.12	7,650.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,100.00

Report Ref No. CC4/LPC21012656/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 5954M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 5954M

RE-INSPECTION

