



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012660/Aqf3n2	
			Date: 20/01/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLB 3691H	Veh. Inspected	SKZ 1337E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103682/AGC	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	14/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	BMW M235i COUPE	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA1J72000V486834	Colour	WHITE	
Odometer	86930 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/12/2021	Inspection Date	28/12/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	