

TP Sompoo
Xiao Chan.

SKZ1337E. 2016 Oct.
BMW M235i Coupe 2979cc
WBA1J72000V486834.

Front Bumper	torn	1580.	✓
Front Bumper Clips.	M	50 (SN)	✓
Front Bumper Side Holder LH.	M	85	X
Front Bumper Sensor	M	265	X
Front Bumper Nozzle Pump.	M	219	X
Headlamp LH.	Wt	2650	✓
	4230	S.N. 180	
	3807		

Panel Beating
Spray Painting.
Wiring.

~~400~~ 250
~~400~~ 250
~~50~~ 30

530

total: 4387

4/51 3.5K. ✓
03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature