

SMRT



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Repair Estimates

SLW 2495 D

|                         |                             |    |                               |
|-------------------------|-----------------------------|----|-------------------------------|
| <b>Parts</b>            | (a) Cost / List Price Items | \$ | 1,154.90                      |
|                         | Plus/Less 20%               | \$ | 230.98                        |
|                         | <b>Total of Cost / List</b> | \$ | <b>923.92</b>                 |
|                         | (b) Nett Price Items        |    |                               |
|                         | Less                        |    |                               |
|                         | <b>Total of Nett Item</b>   |    |                               |
|                         | (c) Special Nett Items      | \$ | 235.00                        |
| <b>Total Parts Cost</b> |                             | \$ | <b>1,158.92</b>               |
| <b>Labour</b>           |                             | \$ | <u>220.00</u> 1,040.00        |
| <b>Total</b>            |                             | \$ | <u>220.00</u> <b>2,198.92</b> |

*Not withain  
Heavy After Rain*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : CLIC  
Survey conducted on : 15/12/21 at 11:09

### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 01 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 15/12/21



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Spare Parts

Vehicle No. : **SLW 2495 D**  
Make & Model : **HONDA VEZEL**  
Chassis No : **RU31222430**

Submit By : **SERENCE**  
Year Manufacture : **2-Feb-18**  
Engine No. :

## Cost / List

| S/No. | Part Description             | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|------------------------------|-----|------------|-------|-------------------------|
| 1     | Reverse sensor               | 1   | \$200.00   | S.N   | X                       |
| 2     | Rear bumper                  | 1   | \$777.90   |       | X                       |
| 3     | Rear bumper clip             | 10  | \$35.00    | S.N   | X                       |
| 4     | Rear bumper side retainer LH | 1   | \$27.50    |       | X                       |
| 5     | Rear bumper side retainer RH | 1   | \$27.50    |       | X                       |
| 6     | Rear bumper reflector LH     | 1   | \$161.00   |       | X                       |
| 7     | Rear bumper reflector RH     | 1   | \$161.00   |       | X                       |
| 8     |                              |     |            |       |                         |
| 9     |                              |     |            |       |                         |
| 10    |                              |     |            |       |                         |
| 11    |                              |     |            |       |                         |
| 12    |                              |     |            |       |                         |
| 13    |                              |     |            |       |                         |
| 14    |                              |     |            |       |                         |
| 15    |                              |     |            |       |                         |
| 16    |                              |     |            |       |                         |
| 17    |                              |     |            |       |                         |
| 18    |                              |     |            |       |                         |
| 19    |                              |     |            |       |                         |
| 20    |                              |     |            |       |                         |
| 21    |                              |     |            |       |                         |
| 22    |                              |     |            |       |                         |
| 23    |                              |     |            |       |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge



(T) 6484 1221 (F) 6484 7829

Submit By : Carmen Lim  
Year of Manufacture : 43133

[illegible]

me