



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Page 1 / 2

FALCON - AIR

CHUA ESTABLISHMENT PRIVATE LIMITED
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
MR NG - 98593338

Attention : Motor Claim Department

Estimate : ES012304

Date : 15/12/2021
Vehicle Num. : GBF 4322P
Make/Model : NISSAN CABSTAR-2016
Chassis/Eng#: JN1SC2F24Z0859013
Accident Date : 10/12/2021
Claim No. : SNM21D207195/C02
Reference : TP - GEG AGT CHINA
Policy No. : 2021-V0118818

*Not withair
11km @ 3050ph
Purvey Air Pain
4 days*

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	NETT ITEMS: 1395-70 TAILGATE		1,459.60 ✓
2.	1 PC	TAILGATE STICKER (NISSAN) 458		169.00 ✓
3.	1 PC	REAR END PANEL		846.80 ✓
4.	1 PC	LH TAILGATE LOCK		56.00 ✓
5.	1 PC	LH CORNER PANEL		182.90 ✓
6.	2 PCS	LH CORNER PANEL RUBBER	12.00	24.00 ✓
7.	2 PCS	LH TAILLAMP	CM 266.30 ✓	532.60 ✓

Nett Total S\$: 3,270.90
10.00% Discount S\$: 327.09
2,943.81

1.	1 PC	SPECIAL NETT ITEMS : 70 km/h STICKER		25.00 125m ✓
2.	1 PC	STICKER - 13 PAX		25.00 125m ✓
3.	1 PC	REAR STEP PANEL		200.00 80m ✓
4.	1 SET	REVERSE SENSOR		280.00 200m ✓
5.	1 PC	REAR NUMBER PLATE		40.00 X ✓

Special Nett Total S\$: 570.00

LABOUR :
TO RUSTPROOF ACCIDENT DAMAGE AREA 150.00 601

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

 Page 2 / 2
 Co. Reg. No.: 199501140D
 GST Reg. No.: 199501140D

FALCON - AIR

 FALCON AIR AUTO SERVICES PTE LTD
 176 SIN MING DRIVE #01-06/07
 SIN MING AUTOCARE 575721
 TEL: 6789-7997 FAX: 6788-7997
 NG - 98593338

Attention: Motor Claim Department

Estimate : ES012304

 Date : 15/12/2021
 Vehicle Num. : GBF 4322P
 Make/Model : NISSAN CABSTAR-2016
 Chassis/Eng# : JN1SC2F24Z0859013
 Accident Date : 10/12/2021
 Claim No. : SNM21D207195/C02
 Reference : TP - GEG AGT CHINA
 Policy No. : 2021-V0118818

Quantity	Particular	Unit Price	Amount S\$
	TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER		50.00 ✓
	TO TRANSFER SLIDING DOOR MECHANISM		120.00 X
	TO CUT OUT/REWELD REAR END PANEL, REPAIR REAR FLOOR BOARD, REAR CHASSIS INCLUDING REPLACEMENT OF PARTS TO SPRAY PAINT ON TAILGATE, REAR END PANEL, REAR FLOOR BOARD		700.00 Cool
			800.00 Cool
	Labour Total S\$:		1,820.00

E. & O.E.

Total S\$: 5,333.81

FALCON AIR AUTO SERVICES PTE LTD

This estimate was prepared from visual inspection. Further materials and labour charges may be required when repair is completed. We will advise you accordingly.

 FALCON - AIR AUTO SERVICES PTE LTD
 [a subsidiary of Falcon-Air Holdings Pte Ltd]

 Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Singapore : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg