

REFURBISHMENT ESTIMATE\*

DATE 11/12/2021 1820

VEHICLE NO. SHA9807E

MAKE REG 27.08.2020

MODEL : HYUNDAI IONIQ G3

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT RH WING MIRROR			\$1,391.70
				\$1,391.70
				\$278.34
				\$1,113.02
	Labour Charge			\$120.00
	Panel Beating			\$100.00
	Spray Painting Charge			\$220.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$1,333.02

Kr

680  
80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thavanellkhandu.com  
 482235769  
 11/12/21 1700  
 PIP btr paint photo  
 Labour only ~~with~~  
 1 day wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Date/Time: 14.12.2021 08:32

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4151750

JC NO 305497834

OMER

IS CITYCAB PTE LTD  
OMER NO: 7010070  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65551188 (O)  
(P)

REGN NO:

SHA9807E ✓

MILEAGE

MAKE

HYUNDAI ✓

FUEL

E ..... 1/2 ..... F

MODEL

IONIQ(G3)

DATE/TIME IN 13.12.2021 13:50

YR OF MANU

27.08.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU184468

COMPLETION DATE/TIME:

DUPLICATE CARD NO


JOB DESCRIPTION

Accident Date: 11.12.2021  
DURATION: 3P 11.12.2021

NO

LABOR CODE

DESCRIPTION



ISSUED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Payment Slip

SHA9807E

CHIANG

Exit Pass

SHA9807E

Vehicle No.:

Service Advisor

Signature/Date

Name of Service Advisor

Date

Handed to Service Reception upon collection

To be kept by Security Guard