

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT

Not Authorised
Resurvey Before
3 days

DEAR SIR / MADAM :

Date: 14/12/2021

Page : 1 of 2

ACCIDENT REPAIR ON: SLP5793K
MODEL : COOPER 5DR FWD LED ABS
POLICY NO :
CHASSIS NO : WMWXS520102F22501
YEAR OF MANUFACTURE : 2017
DATE / TIME OF ACCIDENT: 09/12/2021 Time: 0905Hrs at CARPARK OF SILOSO BEACH SENTOSA
THIRD PARTY VEHICLE NO: GBE3931T

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	BONNET		\$ 1,116.00	<i>By</i>	\$ 1,116.00 ✓
2	FRONT GRILLE		\$ 231.00	<i>new</i>	\$ 231.00 ✓
3	FRONT GRILLE TRIM		\$ 125.00		\$ 125.00 ?
4	MINI FRONT HOOD RH		\$ 70.00	<i>n</i>	\$ 70.00 X
5	MINI FRONT HOOD LH		\$ 70.00	<i>n</i>	\$ 70.00 X
6	MINI LOGO EMBLEM		\$ 66.00	<i>new</i>	\$ 66.00 ✓
7	FRONT BUMPER REINFORMENT BAR		\$ 378.00		\$ 378.00 ?
8	IMPACT ASBORDER SPONGE		\$ 53.00	<i>new</i>	\$ 53.00 X
9	ENGINE BONNET SEAL		\$ 35.00	<i>new lot</i>	\$ 35.00 ✓

Sub-Total: 2,109.00

Less: 10% discount - 210.90

Total Parts after 10% discount: 1,898.10

Special Nett Items

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1	Anti-rust coating	2	80.00	160.00	301
				160.00	

Total Parts: 2,058.10

Labour Charges For Rear Portion

- | | | | |
|---|---|----------|-----|
| 1 | Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts. | 1,500.00 | 40d |
| 2 | Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities | 1,500.00 | 25d |
| 3 | Provide skill labour to disconnect and check electrical wiring | 150.00 | 2d |

Total Labour:

Total Parts & Labour:	3,150.00
GST 7%	5,208.10
Grand Total:	364.57
	5,572.67

Estimate Repair Duration

~~10 days~~

3 days

Page : 2 of 2

ACCIDENT VEHICLE OF : SLP5793K

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: NINJA LO

Survey attended by:

Name : Kenneth
 Company : ELK
 Date : 15/12/21
 Time : 10.55am
 Contact No : _____
 Email : _____