

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#09-16 AIG Building

Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

Not Auth'd
Resurvey Bepain

3 days

\$2003.20

DEAR SIR / MADAM :

Date: 14/12/2021

Page : 1 of 2

ACCIDENT REPAIR ON: SLP5793K

MODEL : COOPER 5DR FWD LED ABS

POLICY NO :

CHASSIS NO : **WMWXS520102F22501**

YEAR OF MANUFACTURE : **2017**

DATE / TIME OF ACCIDENT: 09/12/2021 Time: 0905Hrs at CARPARK OF SILOSO BEACH SENTOSA

THIRD PARTY VEHICLE NO: **GBE3931T**

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	BONNET		\$ 1,116.00	<i>Ry</i>	\$ 1,116.00 ✓
2	FRONT GRILLE		\$ 231.00	<i>nd</i>	\$ 231.00 ✓
3	FRONT GRILLE TRIM		\$ 125.00	<i>Sn</i>	\$ 125.00 X
4	MINI FRONT HOOD RH		\$ 70.00	<i>n</i>	\$ 70.00 X
5	MINI FRONT HOOD LH		\$ 70.00	<i>n</i>	\$ 70.00 X
6	MINI LOGO EMBLEM		\$ 66.00	<i>nd</i>	\$ 66.00 ✓
7	FRONT BUMPER REINFORMENT BAR		\$ 378.00	<i>R</i>	\$ 378.00 X
8	IMPACT ASBORDER SPONGE		\$ 53.00	<i>Sn</i>	\$ 53.00 X
9	ENGINE BONNET SEAL		\$ 35.00	<i>nd</i>	\$ 35.00 ✓

Sub-Total: 2,109.00

Less: 10% discount - 210.90

Total Parts after 10% discount: 1,898.10

Special Nett Items

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1	Anti-rust coating	NEC	2	80.00	160.00	301
					160.00	

Total Parts: 2,058.10

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00	400
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,500.00	250
3	Provide skill labour to disconnect and check electrical wiring	150.00	20

Total Labour:

Total Parts & Labour: 3,150.00
 GST 7% 5,208.10
 Grand Total: 364.57
 5,572.67

Estimate Repair Duration

10 days
 3 days

Page : 2 of 2

ACCIDENT VEHICLE OF : SLP5793K

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: NINJA LO

Survey attended by:

Name : Kenneth
 Company : CLK
 Date : 15/12/21
 Time : 10.55am
 Contact No :
 Email :