

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

AIG (PIP)

Date: 14.12.2021

Time: 08:32:41

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305497819
 REGN NO : SHC3496Y ✓
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 24.07.2019
 DATE/TIME IN : 11.12.2021 14:50
 ACCIDENT DATE : 11.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00	X 500 SUC
0002	04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00	/ nec
0003	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/ DT / shf
0004	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	↑
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ nec
0006	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	X SUC
0007	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40	↑
0008	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	50.00	2.00-	50.00	/ 500 (V)
0009	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	/ DT ✓
						SUB-TOTAL : 1,479.56	

JOB NATURE

0000	PB	PANEL BEATING	400.00	350
0001	SP	SPRAYPAINT CHARGE	300.00	250 250 ✓

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305497819
REGN NO : SHC3496Y ✓
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 11.12.2021 14:5
ACCIDENT DATE : 11.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 L	Remove / Refix Reverse Sensor	50.00	70
0003 20-05	RENEW ADVERTISEMENT STICKER-	200.00	✓
SUB-TOTAL :		950.00	

TOTAL : 2,429.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thuvan@Lkhauto.lou
82235769
4
14/12/21 1645
p & p bfr paint photo
2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 14.12.2021 08:18

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4151743

JC NO305497819


OMER	REGN NO.: SHC3496Y	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL E.....1/2.....F
OMER NO. 7010045	MODEL IONIQ(G2)	DATE/TIME IN 11.12.2021 14:50
IESS 383 SIN MING DRIVE	YR OF MANU. 24.07.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVKU164831	COMPLETION DATE/TIME:
(R) 65508755 (O)		
(P)		
OUNT CARD NO.		

JOB DESCRIPTION

cident Date: 11.12.2021

ATURE: 3P.11.12.2021

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: **SHC3496Y**

JU AIG

Vehicle No.:

SHC3496Y

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard