

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: j1perfectautowok@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 20.12.2021

TO : **AIG** MOTOR CLAIMS DEPTS *Justin.*
VEHICLE NO : **YN278X**
MODEL : MIT-FE83
DATE OF ACCIDENT : 11.12.2021
TIME OF ACCIDENT : 13:25HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,847.61	\$ 2,847.61 ✓
2	TAILGATE LOWER SUPPORT PANEL <i>Repr</i>	1	\$ 1,842.81	\$ 1,842.81 +
3	TAILGATE HINGE <i>New</i>	4	\$ 189.31	\$ 757.24 T
4	TAILGATE SIDE LOCK <i>Dented RA</i>	2	\$ 241.71	\$ 483.42 <i>241.71</i>
5	TAILGATE STOPPER RUBBER <i>at</i>	2	\$ 54.65	\$ 109.30 <i>54.65</i>
6	TAILGATE STOPPER BRACKET RH <i>Bent</i>	1	\$ 182.71	\$ 182.71 ✓
7	SIDE GATE RH <i>Repr</i>	1	\$ 3,847.10	\$ 3,847.10 x.
8	SIDE GATE LOWER LOCK RH <i>New</i>	1	\$ 274.32	\$ 274.32 ✓
9	SIDE GATE HINGE <i>New</i>	6	\$ 189.31	\$ 1,135.86 +
10	TAIL LAMP RH <i>New</i>	1	\$ 237.21	\$ 237.21 x
11	TAIL LAMP SUPPORT BRACKET RH <i>New</i>	1	\$ 164.71	\$ 164.71 +
12	REAR NUMBER PLATE LAMP <i>New</i>	1	\$ 124.05	\$ 124.05 +
13	REAR CHASSIS CROSSMEMBER <i>New</i>	1	\$ 2,641.70	\$ 2,641.70 T

3326.68
2495.01

TOTAL PRICE \$ 14,648.04
LESS 25% \$ 3,662.01
SUB TOTAL PRICE \$ 10,986.03

CLAIM DETAILS: SPECIAL NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00 x.
2	TAIL GATE '60KM STICKER <i>3</i>	1	\$ 40.00	\$ 40.00 ✓
3	TAIL GATE '10PAX' STICKER <i>1</i>	1	\$ 40.00	\$ 40.00 ✓
4	CARGO BED U CLIP (SPECIAL TYPE) <i>New</i>	6	\$ 180.00	\$ 1,080.00 +
5	REAR CARGO BED CHASSIS (SPECIAL TYPE) <i>New</i>	2	\$ 2,200.00	\$ 4,400.00 +

30

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **YN278X**
 MODEL : **MIT-FE83**
 DATE OF ACCIDENT : 11.12.2021
 TIME OF ACCIDENT : 13:25HRS

TOTAL \$ 5,610.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 1,400.00	600
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,400.00	600
3	BULB CHECKING, WIRING	\$ 180.00	30
4	TRANSFER TAILGATE MECHANISM	\$ 60.00	x
5	REMOVE AND REFIX REAR CARGO BED	\$ 1,800.00	x
6	REAR CHASSIS ALIGNMENT	\$ 250.00	x
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

1230

TOTAL \$5,440.00

TOTAL PARTS COST : \$ 16,596.03
 TOTAL LABOUR COST : \$ 5,440.00
 TOTAL REPAIR COST : \$ 22,036.03

Admin Lj
 r/s 20/12/21.

04 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE
 SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Total: 3755.01

r/s 3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: