

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GOH KWANG ANG
BLK 513D YISHUN STREET 51
#10-335
SINGAPORE 764513

Estimate No: MC1902341
Date: 13 Dec 2021
Policy No: P10647242R00
Veh Reg No: SLT5028R
Make/Model: KIA CERATO K3 1.6A

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: SNA6132S

Estimate Repair Cost to Vehicle No :SLT5028R

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	37.00	
2 REAR BOOT LOGO	1 PC	35.00	
3 REAR BOOT LOCK	1 PC	112.00	
4 REAR BOOT RUBBER	1 PC	100.00	
5 REAR BUMPER	1 PC	668.00	
6 REAR BUMPER REFLECTOR WITH LOWER GARNISH LH	1 PC	347.00	
7 REAR BUMPER SIDE RETAINER LH	1 PC	29.00	
8 REAR BUMPER CLIP	12 PC	36.00	
9 REAR BUMPER REINFORCEMENT	1 PC	313.00	
10 REAR BUMPER BRACKET UPPER LH & RH	2 PC	10.00	
11 REAR BUMPER BRACKET LOWER CENTRE LH & RH	2 PC	16.00	
12 TAILAMP LH	1 PC	788.00	
13 REAR FENDER COWLING LH	1 PC	75.00	
14 REAR FENDER COWLING CLIP	8 PC	24.00	
15 REAR END PANEL GARNISH	1 PC	58.00	
		2,648.00	
	Less 10%	264.80	2,383.20
Special Nett			
16 REVERSE SENSOR SET	1 PC	200.00	
17 BOOT LOGO K3 -CHECK PRICE	1 PC	0.0000	
18 BOOT LOGO CC -CHECK PRICE	1 PC	0.0000	
		200.00	200.00
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
20 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00	
21 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
22 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR BOOT,REAR END PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	
23 TO SPRAY BOOT, REAR BUMPER, REAR END PANEL, REAR FENDER LH	1 PC	850.00	
		1,710.00	1,710.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : GOH KWANG ANG
BLK 513D YISHUN STREET 51
#10-335
SINGAPORE 764513

Estimate No: MC1902341
Date: 13 Dec 2021
Policy No: P10647242R00
Veh Reg No: SLT5028R
Make/Model: KIA CERATO K3 1.6A

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: SNA6132S


Estimate Repair Cost to Vehicle No :SLT5028R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 4,293.20
		Add GST @ 7%	300.52
		Total Amount Payable	S\$ 4,593.72

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FIVE HUNDRED NINETY THREE AND CENTS SEVENTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE