

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MS First Capital Insurance Ltd

36 Robinson Road
 #16-01 City House
 Singapore 068877
 Tel : 6507 - 3848
 Fax : 6507 - 3849

Xiao Tony

Quotation
 DATE : 14.02.2022
 VEH NO : GBF8498P
 MODEL : Toyota Dyna
 D O A : 11.12.2021
 YR REF : GBK3141A

2017 March
JTFAT35Y6d207788

Attn : Motor Claim Dept (pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBF8498P (TOYOTA DYNA)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper <i>NE new</i>	1	645.30 <i>+</i>
2	Front Bumper Bracket - LH & RH <i>NE new</i>	2	380.40 <i>+</i>
3	Front Grille <i>cracked</i>	1	517.50 <i>✓</i>
4	Front Grille Logo <i>new</i>	1	76.90 <i>✓</i>
5	Head Lamp - LH & RH <i>cracked.</i>	2	2,357.40 <i>✓</i>
6	Front Panel <i>Dented.</i>	1	1,194.30 <i>✓</i>
7	Dyna Emblem <i>new</i>	1	71.50 <i>✓</i>
8	Front Corner Panel - LH & RH <i>Ry is</i>	2	596.00 <i>+</i>
9	Front Wing Mirror - LH (Round) <i>NE new</i>	1	105.80 <i>+</i>
10	Front Wing Mirror Stay - LH <i>Broken.</i>	1	277.80 <i>✓</i>
11	Front Windscreen Moulding <i>new</i>	1	278.20 <i>✓</i>
12	Aircon Blower <i>cracked</i>	1	1,335.10 <i>✓</i>
13	Aircon Suction Pipe <i>2 Dented</i>	1	295.40 <i>✓</i>
14	Aircon Discharge Pipe	1	289.50 <i>✓</i>

6693.60
5020.20

\$ 8,421.10
 (2,105.28)
 \$ 6,315.83

Less 25%

S/NET ITEMS

1	Front Number Plate <i>NE new</i>	1	30.00 <i>+</i>
2	Front Grille Clips <i>140</i>	1 set	20.00 <i>✓</i>
3	Front Panel Sealant <i>NE new</i>	1	60.00 <i>✓</i>
4	Front Windscreen Sealant <i>NE new</i>	1	60.00 <i>✓</i>

170.00

Total parts \$ 6,485.83

RE : ESTIMATE FOR ACCIDENT REPAIR GBF8498P (TOYOTA DYNA)

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	1,100.00	800
2	To putty and spray up paint works	\$	1,000.00	700
3	To check wiring system	\$	50.00	30
4	To spray tuffcoat	\$	150.00	60
5	To remove front windscreen	\$	180.00	120
6	To remove dashboard	\$	300.00	220
7	To remove aircon system & top up aircon gas	\$	200.00	120
		\$	2,980.00	

GRAND TOTAL

\$ 9,465.83

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7210.20

h/s: 5750

06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: