

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : SRIRAM SUBRAMANIAN
12 AMBER GARDENS #08-06
KINGS MANSION S(439959)

Estimate No: EST1507642
Date: 14 Dec 2021
Policy No: GA056518
Veh Reg No: SGX3775T
Make/Model: HONDA HONDA CRV
2.0L AT
Chassis No: JHLRE28307C205486
Engine No: R20A11704467
Reg. Date: 22/08/2007

ATTN: INDIA INTERNATIONAL


Your Ref No: TP 1221-6593
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: GBG 8479 P

Estimate Repair Cost to Vehicle No :SGX3775T

<u>Description</u>	<u>U/Price</u>	<u>Quantity</u>	<u>Price</u>	<u>Amount</u>
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 7,333.52
			Add GST @ 7%	513.35
			Total Amount Payable	<u>S\$ 7,846.87</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND EIGHT HUNDRED FORTY SIX AND CENTS EIGHTY SEVEN ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : SRIRAM SUBRAMANIAN
 12 AMBER GARDENS #08-06
 KINGS MANSION S(439959)

Estimate No: EST1507642
Date: 14 Dec 2021
Policy No: GA056518
Veh Reg No: SGX3775T
Make/Model: HONDA HONDA CRV
 2.0L AT
Chassis No: JHLRE28307C205486
Engine No: R20A11704467
Reg. Date: 22/08/2007

ATTN: INDIA INTERNATIONAL

Your Ref No: TP 1221-6593
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: GBG 8479 P

Estimate Repair Cost to Vehicle No :SGX3775T

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT DOOR - RH	1,106.400	1 PC	1,106.40	
2 FRONT DOOR RUBBER - RH	94.5000	1 PC	94.50	
3 FRONT DOOR STICKER - RH	35.0000	1 PCSET	35.00	
4 FRONT DOOR HINGE - RH	44.2000	2 PC	88.40	
5 FRONT DOOR REGULATOR GEAR W/MOTOR - RH	470.7000	1 PC	470.70	
6 FRONT DOOR OUTER MOULDING - RH	94.1000	1 PC	94.10	
7 FRONT DOOR PROTECTOR - RH	156.8000	1 PC	156.80	
8 RHF MUDFLAP - RH	44.3000	1 PCS	44.30	
9 ROCKER PANEL OUTER GARNISH / FRONT - RH	1,290.700	1 PCSSE	1,290.70	
10 SIDE MIRROR ASSY - RH	658.4000	1 PCS	658.40	
11 REAR DOOR - LH	1,077.600	1 PC	1,077.60	
12 REAR DOOR PROTECTOR - LH	113.9000	1 PC	113.90	
13 REAR FENDER WHEEL ARCH GARNISH - LH	88.5000	1 PCS	88.50	
14 REAR DOOR RUBBER - LH	120.0000	1 PCS	120.00	
15 REAR DOOR STICKER - RH	52.6000	1 SET	52.60	
			5,491.90	
		Less 20%	1,098.38	4,393.52
Labour				
16 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	1,200.000	1 JOB	1,200.00	
17 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,400.000	1 JOB	1,400.00	
18 TO TUFF-KOTE	30.0000	1 JOB	30.00	
19 TO CHECK WIRING	50.0000	1 JOB	50.00	
20 TO TRANSFER 2 DOOR AND DOOR FITTING	160.0000	1 JOB	160.00	
21 TO 4 WHEEL ALIGNMENT	100.0000	1 JOB	100.00	
			2,940.00	2,940.00