

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

*Not Authorized
 C/Kle Marcus
 15/12/21
 2/5 @ 3500/
 Teleph. After repair
 5 days*

M/S : SRIRAM SUBRAMANIAN
 12 AMBER GARDENS #08-06
 KINGS MANSION S(439959)

Estimate No: EST1507642
Date: 14 Dec 2021
Policy No: GA056518
Veh Reg No: SGX3775T
Make/Model: HONDA HONDA CRV
 2.0L AT
Chassis No: JHLRE28307C205486
Engine No: R20A11704467
Reg. Date: 22/08/2007

ATTN: INDIA INTERNATIONAL

Your Ref No: TP 1221-6593
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: GBG 8479 P

Estimate Repair Cost to Vehicle No :SGX3775T

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 FRONT DOOR - RH <i>Back 570</i>	1,106.400	1 PC	1,106.40	—
2 FRONT DOOR RUBBER - RH <i>A1</i>	94.5000	1 PC	94.50	X
3 FRONT DOOR STICKER - RH <i>Rec</i>	35.0000	1 PCSET	35.00	—
4 FRONT DOOR HINGE - RH <i>Bent</i>	44.2000	2 PC	88.40	—
5 FRONT DOOR REGULATOR GEAR W/MOTOR - RH <i>Dayad</i>	470.7000	1 PC	470.70	—
6 FRONT DOOR OUTER MOULDING - RH <i>Bent</i>	94.1000	1 PC	94.10	—
7 FRONT DOOR PROTECTOR - RH <i>D/S</i>	156.8000	1 PC	156.80	—
8 RHF MUDFLAP - RH <i>D/S</i>	44.3000	1 PCS	44.30	—
9 ROCKER PANEL OUTER GARNISH / FRONT - RH <i>D/S</i>	1,290.700	1 PCSSE	1,290.70	—
10 SIDE MIRROR ASSY - RH <i>A</i>	658.4000	1 PCS	658.40	X
11 REAR DOOR - RH <i>R</i>	1,077.600	1 PC	1,077.60	X
12 REAR DOOR PROTECTOR - LH <i>Suc</i>	113.9000	1 PC	113.90	X
13 REAR FENDER WHEEL ARCH GARNISH - LH <i>Suc</i>	88.5000	1 PCS	88.50	X
14 REAR DOOR RUBBER - LH <i>17</i>	120.0000	1 PCS	120.00	X
15 REAR DOOR STICKER - RH <i>17</i>	52.6000	1 SET	52.60	X
			5,491.90	
	Less 20%		1,098.38	4,393.52
Labour				
16 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	1,200.000	1 JOB	1,200.00	800
17 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,400.000	1 JOB	1,400.00	1000
18 TO TUFF-KOTE	30.0000	1 JOB	30.00	—
19 TO CHECK WIRING	50.0000	1 JOB	50.00	20
20 TO TRANSFER 1 DOOR AND DOOR FITTING	160.0000	1 JOB	160.00	60
21 TO 4 WHEEL ALIGNMENT	100.0000	1 JOB	100.00	60
			2,940.00	2,940.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : SRIRAM SUBRAMANIAN
12 AMBER GARDENS #08-06
KINGS MANSION S(439959)

ATTN: INDIA INTERNATIONAL

Your Ref No: TP 1221-6593
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: GBG 8479 P

Estimate No: EST1507642
Date: 14 Dec 2021
Policy No: GA056518
Veh Reg No: SGX3775T
Make/Model: HONDA HONDA CRV
2.0L AT
Chassis No: JHLRE28307C205486
Engine No: R20A11704467
Reg. Date: 22/08/2007

Estimate Repair Cost to Vehicle No :SGX3775T

Description	U/Price	Quantity	Price	Amount
			SS	SS
			Total	SS 7,333.52
			Add GST @ 7%	513.35
			Total Amount Payable	SS 7,846.87

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND EIGHT HUNDRED FORTY SIX AND CENTS EIGHTY SEVEN ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-3286-4
208
P-2629-12
1-1970
4599.12
208
3679