

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SFS1110M

Chassis No : JHMRC1890LC202412

Model : ODYSSEY 2.4 EXV-S 20YM (EURO 6)

Owner's Name : CONRAD LIM HANN

Ins Policy No. :

Date of Accident : 8/12/2021

Document No. : SQT21003808 Page 1

Date : 9. Dec 2021

Customer No. : WZ1007

Svc Advisor : JACK NG

Engine No : K24W72501253

Date | Time : 9. Dec 2021 3:35:21 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CONRAD LIM HANN OWNER INSURER: SOMPO INSURANCE ACC DATE: 08/12/2021 SURVEYED BY: DATE: REF NO: TP INSURER: III TP VEH: SLN 5277 U						
04715-T6A-N10ZZ	FACE ASSY, RR. BUMPER / DD	1	571.10	25	428.32	29.98	458.30
33505-SLJ-013	REFLECTOR ASSY, RR. ?	1	48.40	25	36.30	2.54	38.84
71512-T6A-9012M	SPOILER ASSY, R. RR. / CR4	1	99.20	25	74.40	5.21	79.61
71593-T6A-003	SPACER, RR. BUMPER SIDE X	1	20.40	25	15.30	1.07	16.37
71598-T6A-003	SPACER, RR. BUMPER SIDE / CR	1	20.40	25	15.30	1.07	16.37
91505-TM8-003	CLIP, BUMPER / NC	8	2.30	25	13.80	0.97	14.77
68100-T6A-Q10ZZ	TAILGATE COMP / DD ?	1	1141.90	25	856.42	59.95	916.37
74440-T6A-003	WEATHERSTRIP TAILGATE ?	1	125.20	25	93.90	6.57	100.47
34150-T6A-J51	LIGHT ASSY, R. LID ?	1	411.80	25	308.85	21.62	330.47
33500-T6A-J51	LIGHT ASSY, R. TAIL ?	1	893.80	25	670.35	46.92	717.27
66100-T6A-Q01ZZ	PANEL COMP, REAR ?	1	491.40	25	368.55	25.80	394.35
76711-T6A-003	CAPPIVOT / NC	1	5.20	25	3.90	0.27	4.17
73225-TM8-000	RUBBER A WINDSHIELD DAM / NC	1	3.90	25	2.92	0.20	3.12
73226-SZW-000	DAMPER STD 5X5 / NC	2	9.10	25	13.65	0.96	14.61
73221-SR4-000	SPACER, RR. W/SHIELD / NC	4	4.20	25	12.60	0.88	13.48
73216-T6A-003	MOLDING, L. RR. WINDSHIELD CORNER / NC	1	18.00	25	13.50	0.95	14.45
73215-T6A-003	MOLDING, R. RR. WINDSHIELD CORNER / NC	1	18.00	25	13.50	0.95	14.45
73214-T6A-003	MOLDING, RR. WINDSHIELD SIDE / NC	1	19.20	25	14.40	1.01	15.41
Sum Item					2955.96	206.92	3,162.88

Printed on 17/12/2021 8:56:41 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT21003808	Page	2
	64 CECIL STREET	Date	: 9. Dec 2021		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: JACK NG		
Registration No	: SFS1110M	Engine No	: K24W72501253		
Chassis No	: JHMRC1890LC202412	Date Time	: 9. Dec 2021 3:35:21 PM		
Model	: ODYSSEY 2.4 EXV-S 20YM (EURO 6)	Surveyor Name	:		
Owner's Name	: CONRAD LIM HANN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 8/12/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL 120	1	150.00	?	150.00	10.50	160.50
BOJSE	WINDSCREEN SEALANT.	1	150.00	/	150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00	280	380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00	280	380.00	26.60	406.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	800.00	650	800.00	56.00	856.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	800.00	650	800.00	56.00	856.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	650	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS 650	1	800.00	?	800.00	56.00	856.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	/	650.00	45.50	695.50
BKRP21M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS 650	1	4000.00	1300	4000.00	280.00	4280.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) 520	1	3500.00	1040	3500.00	245.00	3745.00
Sum Labor					12510.00	875.70	13385.70

Survey By

Date & Time

Excess

Status

Signature

Steve CLKK

17/12/21, 10:00 am

PIP

by Bel sy

6 dys

Total Amount 15,465.96 1,082.62 16,548.58

Total (Inclusive of GST) 16,548.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/12/2021 8:56:41 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.