

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

15-Dec-21

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1642 A

1 pc	Rear bumper	\$ 459.40	Xr
1 pc	Rear bumper reinforcement	\$ 294.80	Xr
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$ 20.00	Xr
1 pc	Rear bumper reinforcement centre lower bracket	\$ 15.00	Xr
2 pcs	Rear bumper n/s & o/s stay	\$ 276.20	Xr
2 pcs	Rear bumper n/s & o/s side bracket	\$ 66.20	Xr
1 pc	Rear bumper lower moulding centre	\$ 216.50	Xr
1 pc	Rear bumper lower cover	\$ 47.50	Xr
1 pc	Rear bumper cap hook	\$ 9.10	Xr
2 pcs	Rear bumper n/s & o/s reflector @ \$31.90	\$ 63.80	Xr
		\$ 1,468.50	
		\$ 293.70	
		\$ 1,174.80	

### S/Nett

1 set	Rear bumper clips	\$ 48.00	ncc
1 set	Reverse sensor	\$ 280.00	XNN
1 set	End panel inner garnish clips	\$ 38.00	XNN
	Sundry	\$ 50.00	XNN
	To check wiring	\$ 50.00	430
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	XNN
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$ 600.00	180
	To putty and spray painting on rear bumper, end panel, rear bumper moulding (Black), rear bumper lower cover (blue)	\$ 800.00	1330
	To apply rustproofing on the repaired and replaced panels.	\$ 80.00	20
		\$ 3,420.80	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Thuan @ Lkhau b - low  
82235769  
15/12/21 1 Qto 455  
L/S labour only 10 - 20/0  
2 days w/p ✓