



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1008/2021/JT
DATE : 13-Dec-21
WIP : 58130

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul,

12 days - ok - Jy - 31 May 22

OWNER'S NAME : MR CHANDY KUSUMA
ADDRESS : 18 NASSIM HILL
#03-01 TH NASSIM
SINGAPORE 254485
TELEPHONE : HP +65 91852331
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900085534-01
VEHICLE NO : **SML 277 B**
MODEL CODE : AUDI RS 4 AVANT 2.9 TFSI
MODEL YEAR : 17/04/2019
ENGINE NO : DEC 014654
CHASSIS NO : WAUZZZF6KA900543
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Dec-21
PLACE OF ACCIDENT : PATERSON HILL

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 277 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACCUM AND REGAS.	S/N \$	1,700.00	\$	1,700.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$	560.00	\$	560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR BOTH FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	\$	3,000.00
SUB TOTAL LABOUR CHARGES		:	\$ 9,540.00	\$	5,990.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 5,937.00	\$ 4,749.60
2	FRONT BUMPER SECURING STRIP	1	\$ 53.00	
3	FRONT BUMPER SECURING STRIP INNER	1	\$ 36.00	
4	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 334.00	
5	FRONT BUMPER SPOILER (BLACK)	1	\$ 613.00	
6	FRONT BUMPER GRILLE - CENTER	1	\$ 722.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 350.00	
8	FRONT BUMPER LOWER SPOILER TRIM	1	\$ 708.00	
9	FRONT BUMPER SPOILER - LOWER	1	\$ 856.00	
10	FRONT BUMPER SPOILER - LH	1	\$ 676.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 736.00	
12	FRONT AIR GUIDE INNER - LH	1	\$ 75.00	
13	FRONT AIR GUIDE - LH / RH	2	\$ 452.00	
14	RADIATOR GRILLE	1	\$ 4,172.00	\$ 3,337.60
15	"RS4" EMBLEM	1	\$ 128.00	\$ 102.00
16	RADIATOR GRILLE CAP	1	\$ 211.00	\$ 168.80
17	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 102.00	
18	RADIATOR GRILLE UPPER COVER	1	\$ 155.00	
19	RADIATOR GRILLE LOWER COVER	1	\$ 213.00	\$ 170.40
20	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 845.00	\$ 675.60
SUB TOTAL SPARE PARTS		:	\$ 17,374.00	\$ 9,204.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 9,204.00
21	FRONT BUMPER FOAM FILLER PIECE	1	\$ 297.00	\$ 237.60
22	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 134.00	
23	FRONT BUMPER BRACKET - LH	1	\$ 228.00	\$ 182.00
24	FRONT BUMPER TOP COVER	1	\$ 242.00	\$ 193.60
25	"CAUTION" STICKER	1	\$ 14.00	\$ 10.88
26	AIR COND STICKER	1	\$ 8.00	\$ 5.68
27	FRONT LOCK CARRIER BRACKET	1	\$ 244.00	\$ 195.20
28	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00	\$ 44.96
29	POP RIVET	4	\$ 4.00	\$ 2.56
30	HORN - LH	1	\$ 201.00	
31	HORN SUPPORT - LH	1	\$ 50.00	
32	FRONT APARKING AID SENSOR - INNER / OUTER	2	TBC	
33	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	\$ 7.28
34	FRONT BUMPER WIRING SET	1	\$ 510.00	
35	LICENCE PLATE SUPPORT	1	\$ 621.00	\$ 496.80
36	FRONT FENDER - LH	1	\$ 5,665.00	\$ 4,532.00
37	POP RIVET	3	\$ 10.00	\$ 7.92
38	FRONT FENDER CLOING ELEMENT - LH	1	\$ 72.00	\$ 57.52
39	FRONT FENDER BRACKET - LH	1	\$ 35.00	\$ 27.92
40	FRONT FENDER RETAINER - LH	1	\$ 49.00	
SUB TOTAL SPARE PARTS		:	\$ 8,451.00	\$ 15,205.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
		<i>c/f</i>		\$	15,205.92
41	FRONT FENDER TRIM - LH	1	\$	402.00	\$ 321.60
42	FRONT FENDER ADAPTER - LH	1	\$	86.00	
43	FRONT FENDER BRACE - LH	1	\$	118.00	
44	FRONT FENDER BRACKET CENTER- LH	1	\$	49.00	
45	FRONT FENDER BRACKET BACK - LH	1	\$	32.00	
46	FRONT FENDER CLOSING ELEMENT - LH	1	\$	33.00	
47	FRONT WHEEL HOUSING LINER - LH	1	\$	296.00	
48	FRONT BACK PANEL COVER - LH	1	\$	26.00	
49	FRONT WHEEL SPOILER	1	\$	264.00	
50	FRONT SPOILER - LH	1	\$	35.00	
51	STONE CHIP GUARD - LH	1	\$	51.00	
52	FRONT FENDER FLEDGE COVER LONG - LH	1	\$	31.00	\$ 24.64
53	FRONT FENDER FLDGE COVER SHORT - LH	1	\$	23.00	\$ 17.92
54	BONNET	1	\$	3,246.00	\$ 2,596.80
55	BONNET HINGE - LH / RH	2	\$	610.00	\$ 487.20
56	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	84.00	\$ 65.68
57	BONNET GAS FILLED	2	\$	241.00	
58	BONNET SOUND ABSORBER	1	\$	343.00	
59	BONNET SOUND ABSORBER OUTER	1	\$	215.00	\$ 171.60
60	BONNET STRIKER - LH / RH	2	\$	100.00	\$ 39.92
SUB TOTAL SPARE PARTS		:	\$	6,285.00	\$ 18,931.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	18,931.28
61	BONNET LOCK	2	\$	427.00	\$ 170.80
62	CONNECTOR HOUSING	2	\$	26.00	
63	CONNECTOR HOUSING BRAKET	2	\$	19.00	
64	BONNET BOWDEN CABLE - CENTER	1	\$	58.00	
65	BONNET BOWDEN CABLE COVER	1	\$	10.00	
66	BONNET BOWDEN CABLE - OUTER	1	\$	58.00	\$ 46.00
67	BONNET RELEASE LEVER	1	\$	14.00	
68	BONNET LOCK CABLE	1	\$	74.00	
69	PLENUM CHAMBER	1	\$	97.00	
70	HEADLIGHT MATRIX BEAM - LH	1	\$	13,044.00	\$ 10,435.20
71	HEADLIGHT POWER MODULE	1	\$	1,206.00	
72	HEADLIGHT CONTROL UNIT	1	\$	751.00	
73	HEADLIGHT HOSE	1	\$	36.00	
74	SPACER	3	\$	122.00	
75	LIFT CYLINDER - LH	1	\$	210.00	
76	LIFT CYLINDER BRACKET	1	\$	6.00	
77	LIFT CYLINDER CORRUGATED PIPE	1	\$	93.00	
78	FRONT LOCK CARRIER	1	\$	1,332.00	\$ 1,065.60
79	RADIATOR COOLANT SUPPORT	2	\$	76.00	\$ 30.32
80	AIRCOND CONDENSER	1	\$	622.00	\$ 497.60
SUB TOTAL SPARE PARTS		:	\$	18,281.00	\$ 31,176.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	31,176.80
81	HIGH PRESSURE VALVE	1	\$ 51.00		
82	A/C PRESSURE SENSOR	1	\$ 186.00	\$	148.80
83	REFRIGERANT LINE - SUCTION	1	\$ 167.00		
84	REFRIGERANT LINE - PRESSURE HOSE	1	\$ 340.00		
85	REFRIGERANT LINE - SUCTION FRONT	1	\$ 248.00		
86	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 19.00	\$	14.56
87	AIR COOLER CHARGED	1	\$ 1,340.00	\$	1,072.00
88	RADIATOR COOLANT COOLER	1	\$ 1,190.00	\$	952.00
89	RADIATOR ADDITIONAL COOLER - CENTER	1	\$ 2,724.00		
90	RADIATOR ADDITIONAL COOLER - SUPERCOOLING LEVEL	1	\$ 2,545.00		
91	RADIATOR AIR GUIDE	1	\$ 42.00		
92	RADIATOR RUBBER BUSH LOWER INSULATOR	2	\$ 18.00		
93	RADIATOR RUBBER BUSH MOUNTING LOWER	2	\$ 25.00		
94	RADIATOR FAN RING	1	\$ 306.00	\$	244.80
95	RADIATOR FAN CONTROL UNIT - LH / RH	2	\$ 3,018.00		
96	RADIATOR AIR GUIDE LH - INNER / OUTER	2	\$ 93.00	\$	73.44
97	RADIATOR AIR GUIDE RH - INNER / OUTER	2	\$ 93.00	\$	24.32
98	RADIATOR AIR GUIDE - LOWER FRONT	1	\$ 46.00		
99	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 38.00		
100	RADIATOR AIR GUIDE - RH	1	\$ 109.00		
SUB TOTAL SPARE PARTS		:	\$ 12,598.00	\$	33,706.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 33,706.72
101	RADIATOR COOLANT	6	\$ 266.00	\$ 212.64
102	RADIATOR INTAKE AIR DUCT - RH	1	\$ 22.00	
103	RADIATOR INTAKE AIR GUIDE HOSE	1	\$ 53.00	
104	RADIATOR INTAKE HOSE	1	\$ 113.00	
105	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	2	\$ 1,282.00	\$ 1,024.00
106	FRONT WINDOW GUIDE TRIM STRIP - LH / RH	2	\$ 594.00	
107	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
108	SUPPLEMENTARY		\$ 1,384.00	\$ 1,107.20
109	SUNDRIES		\$ 500.00	\$ 53.84
TOTAL SPARE PARTS		:	\$ 67,263.00	\$ 36,164.40
TOTAL LABOUR CHARGES		:	\$ 16,924.00	\$ 9,124.00
GRAND TOTAL		:	\$ 84,187.00	\$ 45,288.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-18/02/22



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1008/2021/JT 20-Dec-21 CHANG 1 of 1 SML 277 B AUDI RS 4 AVANT 2.9 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	FLAT CONTACT HOUSING	1	\$ 16.00	\$ 12.80
2	PRESSURE PIPE	1	\$ 1,368.00	\$ 1,094.40
GRAND TOTAL			\$ 1,384.00	\$ 1,107.20

For Premium Automobiles Pte Ltd

 Authorised Signature