



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1008/2021/JT
DATE : 13-Dec-21
WIP : 58130

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHANDY KUSUMA
ADDRESS : 18 NASSIM HILL
#03-01 TH NASSIM
SINGAPORE 254485
TELEPHONE : HP +65 91852331
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900085534-01
VEHICLE NO : **SML 277 B**
MODEL CODE : AUDI RS 4 AVANT 2.9 TFSI
MODEL YEAR : 17/4/2019
ENGINE NO : DEC 014654
CHASSIS NO : WAUZZZF6KA900543
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Dec-21
PLACE OF ACCIDENT : PATERSON HILL



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 277 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ / 480.00 /	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ / 400.00 250 /	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACCUM AND REGAS.	S/N \$ / 1,700.00 /	
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$ / 560.00 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR BOTH FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ / 6,400.00 3000 /	
SUB TOTAL LABOUR CHARGES		: \$ 9,540.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 277 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS.	S 7,000.00	2750 ✓
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S 384.00	✓
TOTAL LABOUR CHARGES		: \$ 16,924.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS	
			S/NETT			
1	FRONT BUMPER <i>OK</i>	1	\$	5,937.00	<i>4749.60</i>	
2	FRONT BUMPER SECURING STRIP <i>? XAN</i>	1	\$	53.00		
3	FRONT BUMPER SECURING STRIP INNER <i>? XAN</i>	1	\$	36.00		
4	FRONT BUMPER AIR GUIDE - LH / RH <i>? XAN</i>	2	\$	334.00		
5	FRONT BUMPER SPOILER (BLACK) <i>? XAN</i>	1	\$	613.00		
6	FRONT BUMPER GRILLE - CENTER <i>? XAN</i>	1	\$	722.00		
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>? XAN</i>	1	\$	350.00		
8	FRONT BUMPER LOWER SPOILER TRIM <i>? XAN</i>	1	\$	708.00		
9	FRONT BUMPER SPOILER - LOWER <i>? XAN</i>	1	\$	856.00		
10	FRONT BUMPER SPOILER - LH <i>? XAN</i>	1	\$	676.00		
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>? XAN</i>	1	\$	736.00		
12	FRONT AIR GUIDE INNER - LH <i>? XAN</i>	1	\$	75.00		
13	FRONT AIR GUIDE - LH / RH <i>? XAN</i>	2	\$	452.00		
14	RADIATOR GRILLE <i>OK</i>	1	\$	4,172.00		<i>3337.60</i>
15	"RS4" EMBLEM <i>OK</i>	1	\$	128.00		<i>102</i>
16	RADIATOR GRILLE CAP <i>? MIS</i>	1	\$	211.00		<i>168.80</i>
17	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>? XAN</i>	2	\$	102.00		
18	RADIATOR GRILLE UPPER COVER <i>? XAN</i>	1	\$	155.00		
19	RADIATOR GRILLE LOWER COVER <i>? OK</i>	1	\$	213.00		<i>170.40</i>
20	FRONT BUMPER REINFORCEMENT BEAM <i>BT</i>	1	\$	845.00		<i>675.60</i>
SUB TOTAL SPARE PARTS			\$	17,374.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER FOAM FILLER PIECE <i>cm</i>	1	\$ 297.00	237.60
22	FRONT BUMPER GUIDE SECTION - LH / RH <i>? xnn</i>	2	\$ 134.00	
23	FRONT BUMPER BRACKET - LH <i>? cm</i>	1	\$ 228.00	182
24	FRONT BUMPER TOP COVER <i>de</i>	1	\$ 242.00	193.60
25	"CAUTION" STICKER <i>ne</i>	1	\$ 14.00	10.88
26	AIR COND STICKER <i>ne</i>	1	\$ 8.00	5.68
27	FRONT LOCK CARRIER BRACKET <i>? bt</i>	1	\$ 244.00	195.20
28	FRONT BUMPER SUPPORT - LH / RH <i>cm/ne</i>	2	\$ 58.00	44.96
29	POP RIVET <i>ne</i>	4	\$ 4.00	2.56
30	HORN - LH <i>? xnn</i>	1	\$ 201.00	
31	HORN SUPPORT - LH <i>? xnn</i>	1	\$ 50.00	
32	FRONT APARKING AID SENSOR - INNER / OUTER <i>? xnn</i>	2	TBC	
33	FRONT PARKING AID SENSOR SEAL RING <i>ne</i>	4	\$ 9.00	7.28
34	FRONT BUMPER WIRING SET <i>? xnn</i>	1	\$ 510.00	
35	LICENCE PLATE SUPPORT <i>cut</i>	1	\$ 621.00	496.80
36	FRONT FENDER - LH <i>bt</i>	1	\$ 5,665.00	4532
37	POP RIVET <i>ne</i>	3	\$ 10.00	7.92
38	FRONT FENDER CLOING ELEMENT - LH <i>ne</i>	1	\$ 72.00	57.52
39	FRONT FENDER BRACKET - LH <i>bt</i>	1	\$ 35.00	27.92
40	FRONT FENDER RETAINER - LH <i>? xnn</i>	1	\$ 49.00	
SUB TOTAL SPARE PARTS		:	\$ 8,451.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER TRIM - LH <i>de/</i>	1	\$ 402.00	321.60
42	FRONT FENDER ADAPTER - LH <i>? xnn</i>	1	\$ 86.00	
43	FRONT FENDER BRACE - LH <i>? xnn</i>	1	\$ 118.00	
44	FRONT FENDER BRACKET CENTER - LH <i>? xnn</i>	1	\$ 49.00	
45	FRONT FENDER BRACKET BACK - LH <i>? xnn</i>	1	\$ 32.00	
46	FRONT FENDER CLOSING ELEMENT - LH <i>? xnn</i>	1	\$ 33.00	
47	FRONT WHEEL HOUSING LINER - LH <i>? xnn</i>	1	\$ 296.00	
48	FRONT BACK PANEL COVER - LH <i>? xnn</i>	1	\$ 26.00	
49	FRONT WHEEL SPOILER <i>x xnn</i>	1	\$ 264.00	
50	FRONT SPOILER - LH <i>x xnn</i>	1	\$ 35.00	
51	STONE CHIP GUARD - LH <i>? xnn</i>	1	\$ 51.00	
52	FRONT FENDER FLEDGE COVER LONG - LH <i>nee/</i>	1	\$ 31.00	24.64
53	FRONT FENDER FLDGE COVER SHORT - LH <i>nee/</i>	1	\$ 23.00	17.92
54	BONNET <i>bt/</i>	1	\$ 3,246.00	2596.80
55	BONNET HINGE - LH / RH <i>? bt/</i>	2	\$ 610.00	487.20
56	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>nee/</i>	3	\$ 84.00	65.68
57	BONNET GAS FILLED <i>x nn</i>	2	\$ 241.00	
58	BONNET SOUND ABSORBER <i>x nn</i>	1	\$ 343.00	
59	BONNET SOUND ABSORBER OUTER <i>nee/</i>	1	\$ 215.00	171.60
60	BONNET STRIKER - LH / RH <i>bt/</i>	1	\$ 100.00	39.92
SUB TOTAL SPARE PARTS			\$ 6,285.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	BONNET LOCK <i>bt/LH</i>	<i>1</i>	\$ 427.00	<i>170.80</i>
62	CONNECTOR HOUSING <i>? xan</i>	2	\$ 26.00	
63	CONNECTOR HOUSING BRACKET <i>? xan</i>	2	\$ 19.00	
64	BONNET BOWDEN CABLE - CENTER <i>? xan</i>	1	\$ 58.00	
65	BONNET BOWDEN CABLE COVER <i>? xan</i>	1	\$ 10.00	
66	BONNET BOWDEN CABLE - OUTER <i>? cut</i>	1	\$ 58.00	<i>46.00</i>
67	BONNET RELEASE LEVER <i>? xan</i>	1	\$ 14.00	
68	BONNET LOCK CABLE <i>? xan</i>	1	\$ 74.00	
69	PLENUM CHAMBER <i>X xan</i>	1	\$ 97.00	
70	HEADLIGHT MATRIX BEAM - LH <i>ca</i>	1	\$ 13,044.00	<i>10435.20</i>
71	HEADLIGHT POWER MODULE <i>? xan</i>	1	\$ 1,206.00	
72	HEADLIGHT CONTROL UNIT <i>? xan</i>	1	\$ 751.00	
73	HEADLIGHT HOSE <i>? xan</i>	1	\$ 36.00	
74	SPACER <i>? xan</i>	3	\$ 122.00	
75	LIFT CYLINDER - LH <i>? xan</i>	1	\$ 210.00	
76	LIFT CYLINDER BRACKET <i>? xan</i>	1	\$ 6.00	
77	LIFT CYLINDER CORRUGATED PIPE <i>? xan</i>	1	\$ 93.00	
78	FRONT LOCK CARRIER <i>ca</i>	1	\$ 1,332.00	<i>1065.60</i>
79	RADIATOR COOLANT SUPPORT <i>? bt</i>	2	\$ 76.00	<i>30.32</i>
80	AIRCOND CONDENSER <i>? bt</i>	1	\$ 622.00	<i>497.60</i>
SUB TOTAL SPARE PARTS		:	\$ 18,281.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
81	HIGH PRESSURE VALVE ? Xnn	1	\$	51.00	
82	A/C PRESSURE SENSOR ? nm/	1	\$	186.00	148.80
83	REFRIGERANT LINE - SUCTION ? Xnn	1	\$	167.00	
84	REFRIGERANT LINE - PRESSURE HOSE ? Xnn	1	\$	340.00	
85	REFRIGERANT LINE - SUCTION FRONT ? Xnn	1	\$	248.00	
86	OUTSIDE TEMPERATURE SENSOR BRACKET ? bt/	1	\$	19.00	14.56
87	AIR COOLER CHARGED ? bt/	1	\$	1,340.00	1072.00
88	RADIATOR COOLANT COOLER ? bt/	1	\$	1,190.00	952.00
89	RADIATOR ADDITIONAL COOLER - CENTER ? Xnn	1	\$	2,724.00	
90	RADIATOR ADDITIONAL COOLER - SUPERCOOLING LEVEL ? Xnn	1	\$	2,545.00	
91	RADIATOR AIR GUIDE ? Xnn	1	\$	42.00	
92	RADIATOR RUBBER BUSH LOWER INSULATOR ? Xnn	2	\$	18.00	
93	RADIATOR RUBBER BUSH MOUNTING LOWER ? Xnn	2	\$	25.00	
94	RADIATOR FAN RING ? nm/	1	\$	306.00	244.80
95	RADIATOR FAN CONTROL UNIT - LH / RH ? Xnn	2	\$	3,018.00	
96	RADIATOR AIR GUIDE LH - INNER / OUTER ? ca/	2	\$	93.00	73.44
97	RADIATOR AIR GUIDE RH - INNER / OUTER ? ca/	2	\$	93.00	24.32
98	RADIATOR AIR GUIDE - LOWER FRONT ? Xnn	1	\$	46.00	
99	RADIATOR AIR GUIDE - UPPER / LOWER ? Xnn	2	\$	38.00	
100	RADIATOR AIR GUIDE - RH ? Xnn	1	\$	109.00	
SUB TOTAL SPARE PARTS			:	\$ 12,598.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	RADIATOR COOLANT <i>nee ✓</i>	6	\$ 266.00	212.64
102	RADIATOR INTAKE AIR DUCT - RH <i>? Xnn</i>	1	\$ 22.00	
103	RADIATOR INTAKE AIR GUIDE HOSE <i>? Xnn</i>	1	\$ 53.00	
104	RADIATOR INTAKE HOSE <i>? Xnn</i>	1	\$ 113.00	
105	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH <i>cut ✓</i>	2	\$ 1,282.00	1024.00
106	FRONT WINDOW GUIDE TRIM STRIP - LH / RH <i>Xnn</i>	2	\$ 594.00	
107	FRONT NO PLATE <i>54 ✓</i>	S/N	\$ 60.00	
108	SUNDRIES <i>? nee ✓</i>		\$ 500.00	53.84

TOTAL SPARE PARTS	:	\$ 65,879.00
TOTAL LABOUR CHARGES	:	\$ 16,924.00
GRAND TOTAL	:	<u>\$ 82,803.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



SP00210
ENTRY DATE
SUBMITTED
VERSION

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Rasul - Hp 90010068
 SURVEYED DATE : 14/12/21 @ 1520
 AUTHORISED DATE :
 EXCESS COST : 10 days
 LIABILITY : EXCESS: TBA
 REMARKS : Repeat
 Resny before paint

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

 **PREMIUM AUTOMOBILES**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1008/2021/JT 20-Dec-21 CHANG 1 of 1 SML 277 B AUDI RS 4 AVANT 2.9 TFSI	
Quantity	Description		Unit Price	Amount
Parts				
1	FLAT CONTACT HOUSING nec ✓	1	\$ 16.00	\$ 12.80
2	PRESSURE PIPE bt ✓	1	\$ 1,368.00	\$ 1,094.40
GRAND TOTAL			\$ 1,384.00	\$ 1,107.20

For Premium Automobiles Pte Ltd

 Authorised Signature